

APPENDIX A
EDR WELL REPORT



EDR DataMap™ EDR Well Search Report

**Buckman
Santa Fe, NM 87506**

November 18, 2005


Inquiry number 01556889.1w

The Standard in Environmental Risk Management Information

440 Wheelers Farms Road
Milford, Connecticut 06461


Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com




EDR DataMap - Well Search

Buckman



Santa Fe, NM

- | | | |
|--------------------|-----------------|----------|
| Listed Water Wells | Railroads | Wetlands |
| Study Boundary | Contour Lines | |
| Roads | Fault Lines | |
| Major Roads | Water | |
| Waterways | Superfund Sites | |



Scale in Miles

GEOCHECK VERSION 2.1 SUMMARY

FEDERAL DATABASE WELL INFORMATION

MAP ID	WELL ID
5	USGS2983750
5	USGS2983747
5	USGS2983749
5	USGS2983748
5	USGS2983746
5	USGS2983745
5	USGS2983744
6	USGS2983896
6	USGS2983895
6	USGS2983743
19	USGS2983894
19	USGS2983893
19	USGS2983892
118	USGS2983888
118	USGS2983890
118	USGS2983889
135	USGS2983886

STATE WATER WELL INFORMATION

MAP ID	WELL ID
1	3413
2	97489
2	97490
2	18915
3	96169
3	96170
7	3338
9	1925
10	12993
11	3507
13	3371
15	4469
17	3339
18	1923
18	1924
20	9425
21	10491
21	12509
22	12444
23	95897
24	8610
25	8326
26	8290
27	11759
28	11395
29	10251
29	10489
29	3034
30	11762
31	12515
31	12470

GEOCHECK VERSION 2.1 SUMMARY

STATE WATER WELL INFORMATION

MAP ID	WELL ID
31	12555
32	12408
33	12043
33	12044
33	11903
33	12864
33	13068
33	12045
34	12378
35	12430
36	12429
37	13147
38	10711
39	10719
40	10432
40	10748
40	10747
41	10825
42	10708
43	10721
44	10284
44	11219
45	10706
46	3273
47	10710
48	10720
49	9546
50	10707
51	10709
52	10431
53	10705
54	10714
55	10717
56	10726
57	10159
57	10158
58	10715
59	10743
60	10724
54	11668
54	2699
57	107082
54	101410
61	97139
61	10713
62	12394
62	10718
63	10725
64	4587
65	10712
66	10716
67	10722
68	10732
69	10434

GEOCHECK VERSION 2.1 SUMMARY

STATE WATER WELL INFORMATION

MAP ID	WELL ID
70	10433
71	10731
72	3095
73	10734
74	10729
75	10730
76	10735
77	10728
78	10733
79	9507
80	10736
81	10727
82	11650
83	10701
83	10702
84	10699
84	10700
85	13000
85	12999
86	10742
87	10703
87	10704
88	10697
88	10698
89	10741
90	9579
91	10826
91	11750
92	10420
93	96668
94	6675
94	10590
95	5032
95	10799
96	11802
97	4667
97	4667
98	5855
98	4538
98	11941
98	9771
98	12498
99	12994
100	13374
101	8917
101	6552
102	12130
102	9127
103	97947
104	12207
105	6479
106	12623
107	12755
107	11694

GEOCHECK VERSION 2.1 SUMMARY

STATE WATER WELL INFORMATION

MAP ID	WELL ID
107	12624
108	13146
109	6526
110	10754
111	5383
112	12629
112	12211
112	8363
113	11980
114	13410
115	10753
115	12221
117	99461
120	97571
120	96567
120	96280
124	96832
125	96694
125	96693
128	95667
129	97570
131	103919
132	100211
133	105938
134	98983
134	98285

PUBLIC WATER SUPPLY SYSTEM INFORMATION

Map ID:	4	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes

Map ID:	6	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes

Map ID:	8	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes

GEOCHECK VERSION 2.1 SUMMARY

PUBLIC WATER SUPPLY SYSTEM INFORMATION

Map ID:	12	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	14	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	16	
PWS ID:	NM3505126	
PWS Name:	SANGRE DE CRISTO WATER COMPANY PO BOX 4670 SANTA FE, NM 87502	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	116	
PWS ID:	NM3571426	
PWS Name:	LONE STAR MOBILE HOME PARK ROUTE 6, BOX 24 SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	119	
PWS ID:	NM3565926	
PWS Name:	SUNSET MOBILE HOME PARK (SANTA FE) 528 AIRPORT ROAD #15 SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	121	
PWS ID:	NM3544526	
PWS Name:	SANTA FE COUNTRY CLUB APARTMENTS 1002 APRPORT RD. SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	121	
PWS ID:	NM3544526	
PWS Name:	SANTA FE COUNTRY CLUB APARTMENTS 1002 APRPORT RD. SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	122	
PWS ID:	NM3545326	
PWS Name:	CASITAS DE SANTA FE 521 AIRPORT ROAD SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes

GEOCHECK VERSION 2.1 SUMMARY

PUBLIC WATER SUPPLY SYSTEM INFORMATION

Map ID:	122	
PWS ID:	NM3545326	
PWS Name:	CASITAS DE SANTA FE 521 AIRPORT ROAD SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	123	
PWS ID:	NM3544626	
PWS Name:	COUNTRY CLUB GARDENS MOBILE HOME PARK 1002 AIRPORT RD. SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	126	
PWS ID:	NM3569826	
PWS Name:	ASI LA MAR TRAILER PARK 181 AIRPORT ROAD SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	126	
PWS ID:	NM3569826	
PWS Name:	ASI LA MAR TRAILER PARK 181 AIRPORT ROAD SANTA FE, NM 87501	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	127	
PWS ID:	NM3570526	
PWS Name:	JEMEZ ROAD MOBILE HOME PARK 507 JEMEZ ROAD, SPACE #40 SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		No
Map ID:	127	
PWS ID:	NM3570526	
PWS Name:	JEMEZ ROAD MOBILE HOME PARK 507 JEMEZ ROAD, SPACE #40 SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		No
Map ID:	130	
PWS ID:	NM3570726	
PWS Name:	SANTA FE MOBILE HOME HACIENDA 1110 OCATE ROAD SPACE 110 SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		Yes
Map ID:	130	
PWS ID:	NM3570726	
PWS Name:	SANTA FE MOBILE HOME HACIENDA 1110 OCATE ROAD SPACE 110 SANTA FE, NM 87505	
PWS currently has or had major violation(s) or enforcement:		Yes

GEOCHECK VERSION 2.1 SUMMARY

PUBLIC WATER SUPPLY SYSTEM INFORMATION

Map ID: 136
PWS ID: NM3538126
PWS Name: VALLE VISTA WATER UTILITY, INC.
PO BOX 2468
SANTA FE, NM 87504
PWS currently has or had major violation(s) or enforcement: Yes

Map ID: 136
PWS ID: NM3538126
PWS Name: VALLE VISTA WATER UTILITY, INC.
PO BOX 2468
SANTA FE, NM 87504
PWS currently has or had major violation(s) or enforcement: Yes

Map ID: 136
PWS ID: NM3538126
PWS Name: VALLE VISTA WATER UTILITY, INC.
PO BOX 2468
SANTA FE, NM 87504
PWS currently has or had major violation(s) or enforcement: Yes

Map ID: 136
PWS ID: NM3538126
PWS Name: VALLE VISTA WATER UTILITY, INC.
PO BOX 2468
SANTA FE, NM 87504
PWS currently has or had major violation(s) or enforcement: Yes

Map ID: 137
PWS ID: NM3538126
PWS Name: VALLE VISTA WATER UTILITY, INC.
PO BOX 2468
SANTA FE, NM 87504
PWS currently has or had major violation(s) or enforcement: Yes

USGS TOPOGRAPHIC MAP(S)

35106-E1 TURQUOISE HILL, NM
35106-F1 AGUA FRIA, NM
35106-G1 HORCADO RANCH, NM
35106-G2 WHITE ROCK, NM

AREA RADON INFORMATION

Federal Area Radon Information for Zip Code: 87508

Number of sites tested: 1

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	3.900 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

Federal EPA Radon Zone for SANTA FE County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

GEOCHECK VERSION 2.1 SUMMARY

AREA RADON INFORMATION

Federal Area Radon Information for SANTA FE COUNTY, NM

Number of sites tested: 83

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	4.350 pCi/L	61%	37%	1%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	7.633 pCi/L	0%	100%	0%

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Water Well Information:

Map ID:	5	Site no:	355006106094803
Agency cd:	USGS	Latitude:	355006
Site name:	19N.07E.35.4122C	Dec lat:	35.83502589
Longitude:	1060948	Coor meth:	M
Dec lon:	-106.1639139	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NENWSES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5455	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871024
Date inventoried:	19871026	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	ALLUVIUM,BOLSON DEPOSITS AND OTHER SURFACE I
Well depth:	69	Hole depth:	74
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1988-11-21
Water quality data end date:	1988-11-21	Water quality data count:	1
Ground water data begin date:	1988-01-15	Ground water data end date:	2005-02-15
Ground water data count:	61		

Ground-water levels, Number of Measurements: 61

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	5.33		2005-01-20	5.27	
2004-12-09	5.09		2004-11-09	5.40	
2004-08-31	4.96		2004-07-29	4.87	
2004-06-22	4.86		2004-05-17	3.85	
2004-04-27	4.90		2004-03-17	5.39	
2004-02-09	5.87		2003-11-18	6.22	
2003-09-08	5.92		2003-07-22	5.33	
2003-05-28	4.93		2003-03-26	5.52	
2003-01-14	5.95		2002-12-05	5.96	
2002-10-28	5.95		2002-09-24	5.83	
2002-07-25	5.30		2002-05-21	4.60	
2002-04-24	4.99		2002-03-28	5.33	
2002-02-12	5.47		2002-01-15	5.43	
2001-12-13	5.43		2001-11-20	5.57	
2001-10-16	5.24		2001-09-20	4.74	
2001-08-15	4.80		2001-07-18	4.67	
2001-05-31	3.06		2001-04-25	3.99	
2001-03-29	4.25		2001-02-12	4.90	
2001-01-08	5.06		2000-11-21	5.15	
2000-09-14	4.5		2000-08-16	4.54	
2000-07-20	4.48		2000-06-14	4.17	
2000-04-06	4.69		2000-02-08	4.90	
2000-01-05	4.95		1999-12-16	5.07	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1999-11-12	4.96		1999-10-14	4.67	
1999-09-24	4.19		1999-08-27	3.79	
1999-07-21	4.10		1999-06-23	2.80	
1999-05-19	2.90		1999-04-20	4.79	
1999-03-29	5.10		1999-02-23	4.95	
1997-09-16	3.73		1997-08-14	3.66	
1997-07-22	3.92		1997-06-24	2.29	
1988-01-15	4.85				

Map ID:	5	Site no:	355003106094301
Agency cd:	USGS	Latitude:	355003
Site name:	19N.07E.35.4212A	Dec lat:	35.83419258
Longitude:	1060943	Coor meth:	M
Dec lon:	-106.16252499	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNESES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5470	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871031
Date inventoried:	19871105	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	TESUQUE FORMATION,UNDIFFERENTIATED UNIT
Well depth:	280	Hole depth:	304
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1988-01-15	Ground water data end date:	2005-02-15
Ground water data count:	61		

Ground-water levels, Number of Measurements: 61

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	119.50		2005-01-20	122.19	
2004-12-09	127.62		2004-11-09	132.54	
2004-08-31	137.18		2004-07-29	137.16	
2004-06-22	140.19		2004-05-17	142.32	
2004-04-27	143.86		2004-03-17	147.50	
2004-02-09	149.83		2003-11-18	155.37	
2003-09-08	156.00		2003-07-22	155.42	
2003-05-28	155.80		2003-03-26	154.64	
2003-01-14	155.30		2002-12-05	155.34	
2002-10-28	154.45		2002-09-24	154.04	
2002-07-25	154.30		2002-05-21	152.95	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2002-04-24	153.13		2002-03-28	152.98	
2002-02-12	153.02		2002-01-15	152.60	
2001-12-13	152.23		2001-11-20	152.12	
2001-10-16	152.07		2001-09-20	150.97	
2001-08-15	151.20		2001-07-18	151.38	
2001-05-31	150.58		2001-04-25	151.42	
2001-03-29	151.25		2001-02-12	150.72	
2001-01-08	150.06		2000-11-21	149.83	
2000-09-14	148.76		2000-08-16	148.48	
2000-07-20	147.80		2000-06-14	147.58	
2000-04-06	141.59		2000-02-08	146.69	
2000-01-05	148.17		1999-12-16	147.81	
1999-11-12	147.61		1999-10-14	147.04	
1999-09-24	146.70		1999-08-27	146.13	
1999-07-21	144.85		1999-06-23	143.33	
1999-05-19	139.09		1999-04-20	136.84	
1999-03-29	137.70		1999-02-23	138.40	
1997-09-16	144.14		1997-08-14	143.10	
1997-07-22	144.96		1997-06-24	143.69	
1988-01-15	26.86				

Map ID:	5	Site no:	355003106094303
Agency cd:	USGS	Latitude:	355003
Site name:	19N.07E.35.4212C	Dec lat:	35.83419258
Longitude:	1060943	Coor meth:	M
Dec lon:	-106.16252499	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNESES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5470	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871030
Date inventoried:	19871031	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	ALLUVIUM,BOLSON DEPOSITS AND OTHER SURFACE I
Well depth:	60	Hole depth:	64
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1988-01-15	Ground water data end date:	2005-02-15
Ground water data count:	64		

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, Number of Measurements: 64

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	12.12		2005-01-20	12.17	
2004-12-09	11.84		2004-11-09	12.20	
2004-08-31	11.00		2004-07-29	10.75	
2004-06-22	12.10		2004-05-17	11.11	
2004-04-27	11.91		2004-03-17	12.52	
2004-02-09	12.79		2003-11-18	13.06	
2003-09-08	13.05		2003-07-22	12.64	
2003-05-28	12.04		2003-03-26	12.52	
2003-01-14	12.78		2002-12-05	12.83	
2002-10-28	12.98		2002-09-24	12.80	
2002-07-25	12.48		2002-05-21	11.82	
2002-04-24	11.90		2002-03-28	12.00	
2002-02-12	12.13		2002-01-15	12.09	
2001-12-13	12.05		2001-11-20	12.17	
2001-10-16	12.01		2001-09-20	10.87	
2001-08-15	11.70		2001-07-18	11.34	
2001-05-31	9.75		2001-04-25	10.40	
2001-03-29	10.65		2001-02-12	11.04	
2001-01-08	11.18		2000-11-21	11.53	
2000-09-14	11.44		2000-08-16	11.53	
2000-07-20	11.57		2000-06-14	11.27	
2000-04-06	11.16		2000-02-08	11.29	
2000-01-05	11.50		1999-12-16	11.55	
1999-11-12	11.63		1999-10-14	11.49	
1999-09-24	11.10		1999-08-27	10.64	
1999-07-21	10.74		1999-06-23	9.53	
1999-05-19	10.08		1999-04-20	11.42	
1999-03-29	11.57		1999-02-23	11.50	
1999-01-26	11.50		1997-09-16	9.65	
1997-08-14	9.90		1997-07-22	10.14	
1997-06-24	8.55		1997-05-15	8.73	
1988-08-17	9.88		1988-01-15	11.31	

Map ID:	5	Site no:	355003106094302
Agency cd:	USGS	Latitude:	355003
Site name:	19N.07E.35.4212B	Dec lat:	35.83419258
Longitude:	1060943	Coor meth:	M
Dec lon:	-106.16252499	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNESES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5470	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871102
Date inventoried:	19871104	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	ALLUVIUM,BOLSON DEPOSITS AND OTHER SURFACE I
Well depth:	130	Hole depth:	130
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Peak flow data count: 0
 Water quality data end date: 0000-00-00
 Ground water data begin date: 1988-01-15
 Ground water data count: 63

Water quality data begin date: 0000-00-00
 Water quality data count: 0
 Ground water data end date: 2005-02-15

Ground-water levels, Number of Measurements: 63

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	5.66		2005-01-20	5.32	
2004-12-09	5.09		2004-11-09	4.77	
2004-08-31	5.37		2004-07-29	5.36	
2004-06-22	5.89		2004-05-17	6.50	
2004-04-27	6.89		2004-03-17	7.20	
2004-02-09	7.32		2003-11-18	6.48	
2003-09-08	5.70		2003-07-22	4.02	
2003-05-28	4.71		2003-03-26	4.17	
2003-01-14	5.74		2002-12-05	5.88	
2002-10-28	4.14		2002-09-24	3.67	
2002-07-25	4.03		2002-05-21	3.24	
2002-04-24	3.97		2002-03-28	4.01	
2002-02-12	4.55		2002-01-15	4.22	
2001-12-13	4.34		2001-11-20	4.28	
2001-10-16	3.89		2001-09-20	2.74	
2001-08-15	4.44		2001-07-18	3.43	
2001-05-31	4.56		2001-04-25	4.13	
2001-03-29	4.64		2001-02-12	4.03	
2001-01-08	3.39		2000-11-21	2.92	
2000-09-14	2.27		2000-08-16	2.16	
2000-07-20	1.89		2000-06-14	1.70	
2000-04-06	6.00		2000-02-08	6.40	
2000-01-05	3.86		1999-12-16	3.04	
1999-11-12	2.59		1999-10-14	2.13	
1999-09-24	1.89		1999-08-27	1.37	
1999-07-21	0.70		1999-06-23	-0.04	
1999-05-19	0.55		1999-04-20	4.47	
1999-03-29	4.88		1999-02-23	4.95	
1997-09-16	2.79		1997-08-14	2.27	
1997-07-22	7.81		1997-06-24	2.00	
1997-05-15	1.99		1988-08-17	-1.30	
1988-01-15	-0.28				

Map ID:	5	Site no:	355002106093703
Agency cd:	USGS	Latitude:	355002
Site name:	19N.07E.35.4222C	Dec lat:	35.83391482
Longitude:	1060937	Coor meth:	M
Dec lon:	-106.1608583	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NENESES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5480	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871105
Date inventoried:	19871109	Mean greenwich time offset:	MST

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Local standard time flag: Y	Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Unconfined single aquifer	Aquifer: ALLUVIUM,BOLSON DEPOSITS AND OTHER SURFACE I
Well depth: 60	Hole depth: 60
Source of depth data: reporting agency (generally USGS)	Project number: 463526300
Real time data flag: 0	Daily flow data begin date: 0000-00-00
Daily flow data end date: 0000-00-00	Daily flow data count: 0
Peak flow data begin date: 0000-00-00	Peak flow data end date: 0000-00-00
Peak flow data count: 0	Water quality data begin date: 0000-00-00
Water quality data end date: 0000-00-00	Water quality data count: 0
Ground water data begin date: 1988-01-15	Ground water data end date: 2005-02-15
Ground water data count: 62	

Ground-water levels, Number of Measurements: 62

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	16.66		2005-01-20	16.53	
2004-12-09	16.30		2004-11-09	16.40	
2004-08-31	15.02		2004-07-29	13.16	
2004-06-22	16.48		2004-05-17	16.28	
2004-04-27	16.80		2004-03-17	17.29	
2004-02-09	17.43		2003-11-18	17.75	
2003-09-08	17.72		2003-07-22	17.38	
2003-05-28	16.81		2003-03-26	17.12	
2003-01-14	17.39		2002-12-05	17.44	
2002-10-28	17.58		2002-09-24	17.40	
2002-05-21	16.32		2002-04-24	16.39	
2002-03-28	16.43		2002-02-12	16.03	
2002-01-15	16.40		2001-12-13	16.36	
2001-11-20	16.48		2001-10-16	16.47	
2001-09-20	16.39		2001-08-15	16.25	
2001-07-18	15.68		2001-05-31	14.34	
2001-04-25	14.74		2001-03-29	14.97	
2001-02-12	15.14		2001-01-08	15.30	
2000-11-21	15.65		2000-09-14	16.00	
2000-08-16	16.16		2000-07-20	16.14	
2000-06-14	15.81		2000-04-06	15.52	
2000-02-08	15.54		2000-01-05	15.63	
1999-12-16	15.72		1999-11-12	15.90	
1999-10-14	15.97		1999-09-24	15.67	
1999-08-27	17.23		1999-07-21	15.27	
1999-06-23	9.88		1999-05-11	14.49	
1999-04-20	15.63		1999-03-29	15.81	
1999-02-23	15.78		1997-09-16	13.59	
1997-08-14	14.11		1997-07-22	14.63	
1997-06-24	13.24		1997-05-15	13.28	
1988-08-17	13.81		1988-01-15	15.70	

Map ID: 5	Site no: 355002106093702
Agency cd: USGS	Latitude: 355002
Site name: 19N.07E.35.4222B	Dec lat: 35.83391482
Longitude: 1060937	Coor meth: M
Dec lon: -106.1608583	Latlong datum: NAD27
Coor accr: F	District: 35
Dec latlong datum: NAD83	County: 049
State: 35	Land net: NENESES35 T19N R07E
Country: US	Map scale: 24000
Location map: WHITE ROCK N. MEX.	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Altitude:	5480	Altitude method:	M
Altitude accuracy:	10	Altitude datum:	NGVD29
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871108
Date inventoried:	19871112	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	ALLUVIUM,BOLSON DEPOSITS AND OTHER SURFACE I
Well depth:	169	Hole depth:	170
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1988-01-15	Ground water data end date:	2005-02-15
Ground water data count:	75		

Ground-water levels, Number of Measurements: 75

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	17.25		2005-01-20	16.97	
2004-12-09	16.66		2004-11-09	16.09	
2004-08-31	17.56		2004-07-29	17.91	
2004-06-22	18.74		2004-05-17	19.72	
2004-04-27	20.01		2004-03-17	20.25	
2004-02-09	20.19		2003-11-18	18.68	
2003-09-08	16.86		2003-07-22	15.28	
2003-05-28	16.46		2003-03-26	15.25	
2003-01-14	17.99		2002-12-05	17.98	
2002-10-28	15.19		2002-09-24	14.55	
2002-07-25	15.59		2002-05-21	14.35	
2002-04-24	15.22		2002-03-28	15.32	
2002-02-12	15.83		2002-01-15	15.37	
2001-12-13	15.49		2001-11-20	15.52	
2001-10-16	15.15		2001-09-20	13.60	
2001-08-15	16.34		2001-07-18	15.03	
2001-05-31	16.42		2001-04-25	16.24	
2001-03-29	16.56		2001-02-12	15.12	
2001-01-08	14.01		2000-11-21	13.45	
2000-09-14	12.7		2000-08-16	12.55	
2000-07-20	12.33		2000-06-14	12.12	
2000-04-06	18.70		2000-02-08	18.99	
2000-01-05	13.92		1999-12-16	13.70	
1999-11-12	13.11		1999-10-14	12.49	
1999-09-24	12.16		1999-08-27	11.47	
1999-07-21	10.60		1999-06-23	14.24	
1999-05-19	10.55		1999-04-20	16.31	
1999-03-29	16.75		1999-02-23	17.14	
1999-01-26	17.52		1998-12-17	15.84	
1998-11-24	17.98		1998-10-28	18.07	
1998-09-16	13.76		1998-08-11	17.55	
1998-06-11	14.06		1998-05-07	12.90	
1998-03-31	16.30		1998-02-03	13.82	
1997-12-16	12.90		1997-10-21	18.79	
1997-09-16	14.85		1997-08-14	13.81	
1997-07-22	17.14		1997-06-24	14.58	
1997-05-15	13.81		1988-08-17	4.44	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1988-01-15	5.04				

Map ID:	5	Site no:	355002106093701
Agency cd:	USGS	Latitude:	355002
Site name:	19N.07E.35.4222A	Dec lat:	35.83391482
Longitude:	1060937	Coor meth:	M
Dec lon:	-106.1608583	Latlong datum:	NAD27
Coor accr:	F	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NENESES35 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK N. MEX.	Altitude method:	M
Altitude:	5480	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flood plain		
Site type:	Ground-water other than Spring	Date construction:	19871105
Date inventoried:	19871109	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined single aquifer	Aquifer:	TESUQUE FORMATION, UNDIFFERENTIATED UNIT
Well depth:	294	Hole depth:	300
Source of depth data:	reporting agency (generally USGS)	Project number:	463526300
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1988-01-15	Ground water data end date:	2005-02-15
Ground water data count:	61		

Ground-water levels, Number of Measurements: 61

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	139.74		2005-01-20	142.19	
2004-12-09	149.59		2004-11-09	155.10	
2004-08-31	161.58		2004-07-29	161.53	
2004-06-22	164.74		2004-05-17	167.10	
2004-04-27	170.70		2004-03-17	174.08	
2004-02-09	177.65		2003-11-18	185.56	
2003-09-08	186.62		2003-07-22	186.53	
2003-05-28	186.55		2003-03-26	185.70	
2003-01-14	185.73		2002-12-05	185.57	
2002-10-28	185.50		2002-09-24	184.90	
2002-07-25	185.25		2002-05-21	183.76	
2002-04-24	183.76		2002-03-28	183.59	
2002-02-12	183.36		2002-01-15	183.12	
2001-12-13	182.70		2001-11-20	182.68	
2001-10-16	182.54		2001-09-20	181.84	
2001-08-15	181.18		2001-07-18	181.74	
2001-05-31	179.48		2001-04-25	181.85	
2001-03-29	181.60		2001-02-12	180.94	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2001-01-08	180.38		2000-11-21	180.19	
2000-09-14	179.11		2000-08-16	178.76	
2000-07-20	178.15		2000-06-14	177.08	
2000-04-06	168.32		2000-02-08	174.78	
2000-01-05	178.16		1999-12-16	177.91	
1999-11-12	177.61		1999-10-14	177.03	
1999-09-24	176.70		1999-08-27	176.12	
1999-07-21	175.01		1999-06-23	175.49	
1999-05-19	169.69		1999-04-20	163.23	
1999-03-29	164.14		1999-02-23	165.24	
1997-09-16	173.48		1997-08-14	172.37	
1997-07-22	174.20		1997-06-24	172.86	
1988-01-15	38.96				

Map ID:	6	Site no:	355000106092802
Agency cd:	USGS	Latitude:	355000
Site name:	19N.07E.36.3113 SF-2B	Dec lat:	35.83335929
Longitude:	1060928	Coor meth:	M
Dec lon:	-106.15835826	Latlong datum:	NAD27
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNWSWS36 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK	Altitude method:	M
Altitude:	5540.	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Alluvial or marine terrace		
Site type:	Ground-water other than Spring	Date construction:	19860727
Date inventoried:	19860727	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Not Reported	Aquifer:	SANTA FE FORMATION
Well depth:	824.	Hole depth:	860.
Source of depth data:	owner	Project number:	463523600
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1986-07-27
Water quality data end date:	1986-07-27	Water quality data count:	1
Ground water data begin date:	1986-07-29	Ground water data end date:	2005-02-15
Ground water data count:	77		

Ground-water levels, Number of Measurements: 77

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-15	178.04		2005-01-20	185.43	
2004-12-09	200.65		2004-11-09	209.99	
2004-10-13	214.14		2004-08-31	221.06	
2004-07-29	225.98		2004-06-22	240.63	
2004-05-17	252.36		2004-04-27	262.84	
2004-03-17	287.45		2004-02-09	309.98	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2003-11-18	374.63		2003-09-08	404.61	
2003-07-22	445.42		2003-05-28	435.40	
2003-03-26	468.38		2003-01-14	411.94	
2002-12-05	419.30		2002-10-28	478.26	
2002-09-24	483.70		2002-07-25	452.78	
2002-05-21	455.34		2002-04-24	447.90	
2002-03-28	447.24		2002-02-12	437.94	
2002-01-15	453.00		2001-12-13	450.85	
2001-11-20	455.15		2001-10-16	459.45	
2001-09-20	446.85		2001-08-15	397.82	
2001-07-18	423.45		2001-06-06	403.88	
2001-04-25	442.95		2001-03-29	444.90	
2001-02-12	475.44		2001-01-08	491.42	
2000-11-21	502.98		2000-08-16	482.08	
2000-07-20	472.20		2000-06-14	446.70	
2000-04-06	340.06		2000-02-08	401.77	
2000-01-05	512.35		1999-12-16	513.46	
1999-11-12	515.61		1999-10-14	509.40	
1999-09-24	499.82		1999-09-24	499.73	
1999-08-27	489.03		1999-07-21	479.67	
1999-06-23	450.03		1999-06-23	449.94	
1999-05-19	394.38		1999-04-20	336.52	
1999-03-29	341.34		1999-02-23	354.79	
1998-11-24	406.69		1998-10-28	422.48	
1997-09-16	474.20		1997-08-14	477.85	
1997-07-22	453.98		1997-07-02	497.73	
1997-06-24	501.81				
1988-08-24	205.6				
Note: A nearby site that taps the same aquifer was being pumped.					
1988-07-26	236.3				
Note: A nearby site that taps the same aquifer was being pumped.					
1988-06-08	203.7				
Note: A nearby site that taps the same aquifer was being pumped.					
1988-05-23	154.6				
Note: A nearby site that taps the same aquifer was being pumped.					
1988-05-05	179.9				
Note: A nearby site that taps the same aquifer was being pumped.					
1987-08-25	155.60				
Note: A nearby site that taps the same aquifer was being pumped.					
1987-07-06	143.33				
Note: A nearby site that taps the same aquifer was being pumped.					
1987-05-27	86.35				
Note: A nearby site that taps the same aquifer was being pumped.					
1987-03-11	67.03				
Note: A nearby site that taps the same aquifer was being pumped.					
1987-03-09	79.36				
Note: A nearby site that taps the same aquifer was being pumped.					
1986-10-02	152.20				
Note: A nearby site that taps the same aquifer was being pumped.					
1986-07-29	137.77				
Note: A nearby site that taps the same aquifer was being pumped.					

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	6	Site no:	355000106092801
Agency cd:	USGS	Latitude:	355000
Site name:	19N.07E.36.3113 SF-2A	Dec lat:	35.83335929
Longitude:	1060928	Coor meth:	M
Dec lon:	-106.15835826	Latlong datum:	NAD27
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNWSWS36 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK	Altitude method:	M
Altitude:	5540	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Alluvial or marine terrace		
Site type:	Ground-water other than Spring	Date construction:	19860726
Date inventoried:	19860726	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Not Reported	Aquifer:	SANTA FE FORMATION
Well depth:	1863.	Hole depth:	2000.
Source of depth data:	owner	Project number:	463523600
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1986-07-27
Water quality data end date:	1988-11-21	Water quality data count:	2
Ground water data begin date:	1986-07-29	Ground water data end date:	1999-11-12
Ground water data count:	48		

Ground-water levels, Number of Measurements: 48

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1999-11-12	29.35		1999-10-14	29.13	
1999-09-24	28.97		1999-08-27	28.74	
1999-07-21	28.45		1999-06-23	28.19	
1999-05-19	35.66		1999-04-20	35.48	
1999-03-29	35.34		1999-02-23	34.99	
1998-11-24	34.29		1998-10-28	34.09	
1997-09-16	31.03		1997-08-14	30.86	
1997-07-22	30.67		1997-07-02	30.20	
1997-06-24	30.51		1997-06-04	30.37	
1997-05-15	30.18				
1988-08-20	-1.27				

Note: A nearby site that taps the same aquifer was being pumped.

1988-08-15 -3.18

Note: A nearby site that taps the same aquifer was being pumped.

1988-08-10 -3.3

Note: A nearby site that taps the same aquifer was being pumped.

1988-08-05 -6.18

Note: A nearby site that taps the same aquifer was being pumped.

1988-07-30 -10.45

Note: A nearby site that taps the same aquifer was being pumped.

1988-07-25 -10.34

Note: A nearby site that taps the same aquifer was being pumped.

1988-07-20 -14.42

Note: A nearby site that taps the same aquifer was being pumped.

1988-07-15 -18.32

Note: A nearby site that taps the same aquifer was being pumped.

1988-07-10 -22.91

Note: A nearby site that taps the same aquifer was being pumped.

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel		Date	Feet below Surface	Feet to Sealevel
<hr style="border-top: 1px dashed black;"/>				<hr style="border-top: 1px dashed black;"/>		
1988-07-05	-28.28					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-30	-33.68					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-25	-37.74					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-20	-42.66					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-15	-48.82					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-10	-54.17					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-06-05	-61.37					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-30	-69.21					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-25	-77.68					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-20	-80.86					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-15	-87.13					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-10	-95.53					
Note: A nearby site that taps the same aquifer was being pumped.						
1988-05-05	-102.45					
Note: A nearby site that taps the same aquifer was being pumped.						
1987-08-25						
Note: The site was flowing, but the head could not be measured without additional equipment.						
1987-07-06	-136.6					
Note: A nearby site that taps the same aquifer was being pumped.						
1987-05-27						
Note: The site was flowing, but the head could not be measured without additional equipment.						
1987-03-11	-127.3					
Note: A nearby site that taps the same aquifer was being pumped.						
1987-03-09						
Note: The site was flowing, but the head could not be measured without additional equipment.						
1986-10-02						
Note: The site was flowing, but the head could not be measured without additional equipment.						
1986-07-29						
Note: The site was flowing, but the head could not be measured without additional equipment.						

Map ID:	6	Site no:	355000106092803
Agency cd:	USGS	Latitude:	355000
Site name:	19N.07E.36.3113 SF-2C	Dec lat:	35.83335929
Longitude:	1060928	Coor meth:	M
Dec lon:	-106.15835826	Latlong datum:	NAD27
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNWSWS36 T19N R07E
Country:	US	Map scale:	24000
Location map:	WHITE ROCK		

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Altitude:	5540.	Altitude method:	M
Altitude accuracy:	10	Altitude datum:	NGVD29
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Alluvial or marine terrace		
Site type:	Ground-water other than Spring	Date construction:	19860728
Date inventoried:	19860728	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Not Reported	Aquifer:	SANTA FE FORMATION
Well depth:	346.	Hole depth:	380.
Source of depth data:	owner	Project number:	463523600
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1986-07-28
Water quality data end date:	1986-07-28	Water quality data count:	1
Ground water data begin date:	1986-07-29	Ground water data end date:	2005-02-20
Ground water data count:	93		

Ground-water levels, Number of Measurements: 93

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-20	193.65		2005-02-15	193.65	
2005-01-20	197.23		2004-12-09	204.43	
2004-11-09	209.39		2004-10-13	212.09	
2004-08-31	215.90		2004-07-29	216.82	
2004-06-22	219.58		2004-05-17	221.50	
2004-04-27	223.31		2004-03-17	226.35	
2004-02-09	229.02		2003-11-18	233.89	
2003-09-08	234.38		2003-07-22	234.40	
2003-05-28	234.29		2003-03-26	233.65	
2003-01-14	233.84		2002-12-05	233.25	
2002-10-28	233.00		2002-09-24	232.83	
2002-07-25	232.76		2002-05-21	231.72	
2002-04-24	231.67		2002-03-28	231.39	
2002-02-12	231.15		2002-01-15	230.78	
2001-12-13	230.59		2001-11-20	230.50	
2001-10-16	230.25		2001-09-20	229.70	
2001-08-15	229.19		2001-07-18	229.52	
2001-06-06	229.16		2001-04-25	229.30	
2001-03-29	228.80		2001-02-12	228.40	
2001-01-08	227.99		2000-11-21	227.80	
2000-09-14	226.76		2000-08-16	226.41	
2000-07-20	225.88		2000-06-14	225.04	
2000-04-06	219.25		2000-02-08	223.71	
2000-01-05	225.53		1999-12-16	225.35	
1999-11-12	225.12		1999-10-14	224.62	
1999-09-24	224.21		1999-08-27	223.82	
1999-07-21	222.93		1999-06-23	221.66	
1999-05-19	219.28		1999-04-20	214.95	
1999-03-29	215.61		1999-02-23	216.50	
1997-09-16	221.24		1997-08-14	220.53	
1997-07-22	221.58		1997-07-02	220.40	
1997-06-24	220.59		1997-06-04	220.31	
1988-08-20	174.5				

Note: A nearby site that taps the same aquifer was being pumped.

1988-08-15 180.2

Note: A nearby site that taps the same aquifer was being pumped.

1988-08-10 176.3

Note: A nearby site that taps the same aquifer was being pumped.

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1988-08-05	179.6				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-30	182.7				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-25	180.5				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-20	177.0				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-15	174.5				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-10	158.0				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-07-05	178.4				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-30	174.6				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-25	179.9				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-20	178.0				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-15	172.2				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-10	175.9				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-06-05	172.7				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-30	171.8				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-25	150.0				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-20	152.5				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-15	156.7				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-10	163.8				
	Note: A nearby site that taps the same aquifer was being pumped.				
1988-05-05	165.6				
	Note: A nearby site that taps the same aquifer was being pumped.				
1987-08-25	151.22				
	Note: A nearby site that taps the same aquifer was being pumped.				
1987-07-06	149.42				
	Note: A nearby site that taps the same aquifer was being pumped.				
1987-05-27	92.07				
	Note: A nearby site that taps the same aquifer was being pumped.				
1987-03-11	78.54				
	Note: A nearby site that taps the same aquifer was being pumped.				
1987-03-09	90.78				
	Note: A nearby site that taps the same aquifer was being pumped.				
1986-10-02	152.17				
	Note: A nearby site that taps the same aquifer was being pumped.				
1986-07-29	119.51				
	Note: A nearby site that taps the same aquifer was being pumped.				

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	19	Site no:	354731106072003
Agency cd:	USGS	Latitude:	354731
Site name:	T18N.R08E.17.111C	Dec lat:	35.79194444
Longitude:	1060720	Coor meth:	G
Dec lon:	-106.12222222	Latlong datum:	NAD83
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	Not Reported
Country:	US	Map scale:	24000
Location map:	HORCADO RANCH	Altitude method:	M
Altitude:	5960	Altitude datum:	NGVD29
Altitude accuracy:	20		
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Undulating		
Site type:	Ground-water other than Spring	Date construction:	20030924
Date inventoried:	20040302	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	480	Hole depth:	2495
Source of depth data:	driller	Project number:	86359JD00
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	2003-10-24	Ground water data end date:	2005-01-20
Ground water data count:	12		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-01-20	190.73		2004-11-09	191.61	
2004-10-13	191.56		2004-07-29	190.68	
2004-06-22	189.66		2004-05-17	185.76	
2004-04-27	186.59		2004-03-17	185.69	
2004-02-09	187.33				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-30	185.97				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-16	184.81				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-10-24	186.56				
Note: A nearby site that taps the same aquifer was being pumped.					

Map ID:	19	Site no:	354731106072002
Agency cd:	USGS	Latitude:	354731
Site name:	T18N.R08E.17.111B	Dec lat:	35.79194444
Longitude:	1060720	Coor meth:	G
Dec lon:	-106.12222222	Latlong datum:	NAD83
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	Not Reported
Country:	US	Map scale:	24000
Location map:	HORCADO RANCH		

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Altitude:	5960	Altitude method:	M
Altitude accuracy:	20	Altitude datum:	NGVD29
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Undulating		
Site type:	Ground-water other than Spring	Date construction:	20030924
Date inventoried:	20040302	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Multiple wells (a group of wells that are pumped through a s
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	1340	Hole depth:	2495
Source of depth data:	driller	Project number:	86359JD00
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	2003-10-24	Ground water data end date:	2005-01-20
Ground water data count:	12		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-01-20	187.95		2004-11-09	189.55	
2004-10-13	189.42		2004-07-29	188.29	
2004-06-22	190.01		2004-05-17	188.76	
2004-04-27	187.19		2004-03-17	184.14	
2004-02-09	185.65				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-30	175.23				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-16	173.20				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-10-24	164.83				
Note: A nearby site that taps the same aquifer was being pumped.					

Map ID:	19	Site no:	354731106072001
Agency cd:	USGS	Latitude:	354731
Site name:	T18N.R08E.17.111A	Dec lat:	35.79194444
Longitude:	1060720	Coor meth:	G
Dec lon:	-106.12222222	Latlong datum:	NAD83
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	Not Reported
Country:	US	Map scale:	24000
Location map:	HORCADO RANCH	Altitude method:	M
Altitude:	5960	Altitude datum:	NGVD29
Altitude accuracy:	20		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Undulating		
Site type:	Ground-water other than Spring	Date construction:	20030924
Date inventoried:	20040302	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Multiple wells (a group of wells that are pumped through a s
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	2440	Hole depth:	2495
Source of depth data:	driller	Project number:	86359JD00
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Peak flow data count: 0
 Water quality data end date: 0000-00-00
 Ground water data begin date: 2003-10-24
 Ground water data count: 13

Water quality data begin date: 0000-00-00
 Water quality data count: 0
 Ground water data end date: 2005-01-24

Ground-water levels, Number of Measurements: 13

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-01-24	124.57		2005-01-20	124.66	
2004-11-09	117.94		2004-10-13	116.90	
2004-07-29	113.29		2004-06-22	108.22	
2004-05-17	101.25		2004-04-27	97.27	
2004-03-17	89.10				
2004-02-09	82.41				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-30	70.88				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-12-16	67.20				
Note: A nearby site that taps the same aquifer was being pumped.					
2003-10-24	59.90				
Note: A nearby site that taps the same aquifer was being pumped.					

Map ID:	118	Site no:	353824106040901
Agency cd:	USGS	Site name:	T16N.R08E.2.343A NMOSE County Well Deep Piez
Site name:	T16N.R08E.2.343A NMOSE County Well Deep Piez	Longitude:	1060409
Longitude:	1060409	Dec lat:	35.64
Dec lon:	-106.06916667	Coor meth:	G
Coor accr:	S	Latlong datum:	NAD83
Dec latlong datum:	NAD83	District:	35
State:	35	County:	049
Country:	US	Land net:	Not Reported
Location map:	Agua Fria	Map scale:	24000
Altitude:	6365	Altitude method:	M
Altitude accuracy:	20	Altitude datum:	NGVD29
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flat surface		
Site type:	Ground-water other than Spring	Date construction:	20040315
Date inventoried:	20040518	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	1910	Hole depth:	2000
Source of depth data:	driller	Project number:	86369L422
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	2004-05-14	Ground water data end date:	2005-01-20
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-01-20	209.36		2004-11-09	209.36	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-07-29	209.43				
2004-05-14	209.57				

Note: Other conditions existed that would affect the measured water level.

Map ID:	118	Site no:	353824106040903
Agency cd:	USGS	Site name:	T16N.R08E.2.343C NMOSE County Well Shallow Piez
Longitude:	1060409	Dec lat:	35.64
Dec lon:	-106.06916667	Coor meth:	G
Coor accr:	S	Latlong datum:	NAD83
Dec latlong datum:	NAD83	District:	35
State:	35	County:	049
Country:	US	Land net:	Not Reported
Location map:	Agua Fria	Map scale:	24000
Altitude:	6365	Altitude method:	M
Altitude accuracy:	20	Altitude datum:	NGVD29
Hydrologic:	Rio Grande Santa Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flat surface		
Site type:	Ground-water other than Spring	Date construction:	20040315
Date inventoried:	20040518	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	460	Hole depth:	2000
Source of depth data:	driller	Project number:	86369L422
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	2004-05-14	Ground water data end date:	2005-01-20
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-01-20	185.41		2004-11-09	185.37	
2004-07-29	185.21				
2004-05-14	185.47				

Note: Other conditions existed that would affect the measured water level.

Map ID:	118	Site no:	353824106040902
Agency cd:	USGS	Site name:	T16N.R08E.2.343B NMOSE County Well Middle Piez
Longitude:	1060409	Dec lat:	35.64
Dec lon:	-106.06916667	Coor meth:	G
Coor accr:	S	Latlong datum:	NAD83
Dec latlong datum:	NAD83	District:	35
State:	35	County:	049
Country:	US	Land net:	Not Reported
Location map:	Agua Fria	Map scale:	24000

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Altitude:	6365	Altitude method:	M
Altitude accuracy:	20	Altitude datum:	NGVD29
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Flat surface		
Site type:	Ground-water other than Spring	Date construction:	20040315
Date inventoried:	20040518	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Unconfined multiple aquifers	Aquifer:	SANTA FE FORMATION
Well depth:	1075	Hole depth:	2000
Source of depth data:	driller	Project number:	86369L422
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	2004-05-14	Ground water data end date:	2004-11-09
Ground water data count:	3		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel		Date	Feet below Surface	Feet to Sealevel
2004-11-09	202.29			2004-07-29	203.78	
2004-05-14	203.87					

Note: Other conditions existed that would affect the measured water level.

Map ID:	135	Site no:	353516106035801
Agency cd:	USGS	Latitude:	353516
Site name:	16N.08E.26.32112	Dec lat:	35.58781066
Longitude:	1060358	Coor meth:	M
Dec lon:	-106.06668906	Latlong datum:	NAD27
Coor accr:	S	District:	35
Dec latlong datum:	NAD83	County:	049
State:	35	Land net:	NWNESWS26 T16N R08E
Country:	US	Map scale:	24000
Location map:	TURQUOISE HILL	Altitude method:	M
Altitude:	6285.00	Altitude datum:	NGVD29
Altitude accuracy:	10		
Hydrologic:	Rio GrandeSanta Fe. New Mexico. Area = 1830 sq.mi.		
Topographic:	Valley flat		
Site type:	Ground-water other than Spring	Date construction:	19710422
Date inventoried:	19710422	Mean greenwich time offset:	MST
Local standard time flag:	Y	Type of ground water site:	Single well, other than collector or Ranney type
Aquifer Type:	Not Reported	Aquifer:	TESUQUE FORMATION,UNDIFFERENTIATED UNIT
Well depth:	395	Hole depth:	Not Reported
Source of depth data:	owner	Project number:	463500205
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1973-06-11	Ground water data end date:	2004-10-07
Ground water data count:	221		

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, Number of Measurements: 221

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-10-07	131.53		2004-08-30	131.51	
2004-07-22	131.45		2004-05-07	131.47	
2004-04-16	131.49		2004-03-18	131.39	
2004-02-18	131.40		2004-01-16	131.34	
2003-11-06	131.39		2003-10-09	131.37	
2003-09-19	131.37				
Note: Other conditions existed that would affect the measured water level.					
2003-08-22	132.13		2003-07-18	132.54	
2003-07-11	131.23		2003-06-25	131.41	
2003-04-11	131.22		2003-02-13	130.01	
2003-01-22	130.97		2002-12-12	130.89	
2002-11-25	130.78		2002-10-10	130.94	
2002-09-20	131.15		2002-08-30	131.20	
2002-07-18	131.29		2002-04-18	131.24	
2002-03-06	131.20		2002-02-14	131.15	
2002-01-17	131.63		2001-12-20	131.07	
2001-10-20	131.07				
2001-10-03	131.11				
Note: Other conditions existed that would affect the measured water level.					
2001-10-03	131.11		2001-07-02	131.18	
2001-06-01	131.20				
2001-05-08	131.13				
Note: Other conditions existed that would affect the measured water level.					
2001-03-13	131.13		2001-02-15	131.16	
2001-01-23	131.27		2000-12-20	131.23	
2000-08-02	131.08		2000-05-05	130.92	
2000-04-05	130.83		2000-03-14	130.89	
1999-11-19	131.10		1999-10-28	130.92	
1998-08-05	130.76		1998-05-07	130.65	
1998-04-30	130.60		1998-04-08	130.67	
1998-02-20	130.64		1998-01-29	130.63	
1998-01-22	130.71		1997-11-18	130.76	
1997-02-14	130.73		1996-01-31	130.41	
1995-08-16	130.25		1995-02-11	130.18	
1994-08-22	130.14		1994-02-15	130.08	
1993-08-24	129.80		1993-01-05	129.56	
1992-02-25	128.73		1991-02-27	129.96	
1991-02-26	129.96		1990-02-27	129.34	
1989-04-14	129.29		1989-02-11	129.28	
1988-03-17	129.29		1985-03-21	128.63	
1985-02-26	128.73		1985-01-24	128.65	
1985-01-07	128.65		1984-11-26	128.65	
1984-10-22	128.65		1984-09-26	128.61	
1984-08-31	128.57		1984-07-31	128.51	
1984-06-28	128.50		1984-05-31	128.38	
1984-05-04	128.32		1984-04-10	128.43	
1984-03-07	128.40		1984-02-07	128.36	
1983-12-07	128.34		1983-11-09	128.36	
1983-10-13	128.40		1983-09-13	128.29	
1983-08-17	128.28		1983-07-19	128.21	
1983-06-23	128.17		1983-05-23	128.25	
1983-04-26	128.12		1983-03-30	128.07	
1983-02-28	128.12		1983-02-08	128.06	
1983-02-01	128.07		1983-01-06	128.05	
1982-12-06	128.03		1982-11-08	128.01	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-09-14	127.97		1982-08-17	127.87	
1982-07-19	127.77		1982-06-22	127.71	
1982-05-24	127.71		1982-04-29	127.70	
1982-04-27	127.70		1982-03-31	127.79	
1982-03-09	127.79		1982-02-08	127.72	
1982-01-07	127.82		1981-12-08	127.68	
1981-11-12	127.63		1981-10-19	127.67	
1981-09-23	127.66		1981-08-26	127.53	
1981-06-30	127.61		1981-06-04	127.50	
1981-05-05	127.44		1981-04-09	127.41	
1981-03-11	127.42		1981-02-12	127.47	
1981-01-13	127.36		1980-11-18	127.38	
1980-11-10	127.4		1980-11-05	127.4	
1980-10-31	127.4		1980-10-25	127.2	
1980-09-23	127.36		1980-09-15	127.3	
1980-09-10	127.3		1980-09-05	127.3	
1980-08-31	127.3		1980-08-27	127.29	
1980-08-25	127.3		1980-08-20	127.4	
1980-08-15	127.4		1980-08-10	127.5	
1980-08-05	127.5		1980-07-31	127.6	
1980-07-25	127.5		1980-07-20	127.4	
1980-07-15	127.4		1980-07-10	127.3	
1980-07-05	127.3		1980-06-30	127.25	
1980-06-30	127.3		1980-06-25	127.3	
1980-06-20	127.3		1980-06-15	127.3	
1980-06-10	127.2		1980-06-05	127.2	
1980-05-31	127.2		1980-05-25	127.2	
1980-05-20	127.2		1980-05-15	127.1	
1980-05-10	127.1		1980-05-06	127.11	
1980-04-30	127.1		1980-04-25	127.1	
1980-04-20	127.1		1980-04-15	127.1	
1980-04-10	127.1		1980-04-08	127.13	
1980-03-10	127.19		1980-02-11	127.16	
1980-01-20	127.3		1980-01-15	127.2	
1980-01-14	127.25		1980-01-05	127.2	
1979-12-31	127.3		1979-12-25	127.2	
1979-12-20	127.2		1979-12-15	127.2	
1979-12-12	127.20		1979-11-14	127.25	
1979-11-05	127.3		1979-10-31	127.2	
1979-10-25	127.2		1979-10-23	127.13	
1979-10-20	127.2		1979-10-15	127.2	
1979-10-10	127.2		1979-10-05	127.2	
1979-10-04	127.18		1979-09-25	127.2	
1979-09-24	127.22		1979-09-20	127.1	
1979-09-10	127.15		1979-09-10	127.1	
1979-09-05	127.2		1979-08-31	127.1	
1979-08-25	127.2		1979-08-23	127.14	
1979-08-20	127.1		1979-08-15	127.1	
1979-08-10	127.1		1979-08-05	127.2	
1979-07-31	127.2		1979-07-25	127.2	
1979-07-24	127.17		1979-07-02	127.03	
1979-06-02	127.04		1979-04-30	126.98	
1979-04-06	126.55		1979-03-07	127.00	
1979-02-06	126.62		1979-01-09	126.95	
1978-12-13	127.03		1978-07-23	126.86	

GEOCHECK VERSION 2.1
STATE DATABASE WELL INFORMATION

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1978-02-09	126.78	
1977-07-25	126.65	
1976-08-17	126.39	
1975-08-05	126.16	
1974-10-16	126.03	
1974-06-28	125.93	

Date	Feet below Surface	Feet to Sealevel
1978-01-11	126.77	
1977-01-11	126.62	
1976-02-10	126.35	
1975-02-12	126.11	
1974-07-02	125.87	
1973-06-11	125.62	

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Water Well Information:

Map ID:	1		
Objectid:	3413	Id:	31845
X coord:	397471	Y coord:	3967138
Db file nb:	RG 21318		
Use:	OBSERVATION		
Diversion:	0	Pod rec nb:	31845
Well numbe:	RG 21318	Tws:	19N
Rng:	08E	Sec:	30
Q:	3	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	397521	Northing:	3966935
Start date:	19720630	Finish dat:	19720712
Depth well:	1706	Depth wate:	79

Map ID:	2		
Objectid:	97489	Id:	20371
X coord:	395129	Y coord:	3966528
Db file nb:	RG 38977		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	20371
Well numbe:	RG 38977 -EXPL	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	526500	Y:	1760000
Easting:	0	Northing:	0
Start date:	19821207	Finish dat:	19830110
Depth well:	27	Depth wate:	2

Map ID:	2		
Objectid:	97490	Id:	60371
X coord:	395129	Y coord:	3966528
Db file nb:	RG 38977		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	60371
Well numbe:	RG 38977 -EXPL-2	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	526500	Y:	1760000
Easting:	0	Northing:	0
Start date:	19821209	Finish dat:	19830110
Depth well:	25	Depth wate:	6

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	2		
Objectid:	18915	Id:	172438
X coord:	394985	Y coord:	3966461
Db file nb:	SP 04842		
Use:	MUNICIPAL - CITY OR COUNTY SUPPLIED WATER		
Diversion:	0	Pod rec nb:	172438
Well numbe:	SP 04842	Tws:	19N
Rng:	07E	Sec:	35
Q:	2	Q2:	4
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	395035	Northing:	3966258
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	3		
Objectid:	96169	Id:	16146
X coord:	395127	Y coord:	3966314
Db file nb:	RG 26485		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	16146
Well numbe:	RG 26485	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	526500	Y:	1759300
Easting:	0	Northing:	0
Start date:	19750918	Finish dat:	19750918
Depth well:	95	Depth wate:	13

Map ID:	3		
Objectid:	96170	Id:	44926
X coord:	395127	Y coord:	3966314
Db file nb:	RG 26486		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	44926
Well numbe:	RG 26486	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	526500	Y:	1759300
Easting:	0	Northing:	0
Start date:	19750919	Finish dat:	19750919
Depth well:	100	Depth wate:	11

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	7		
Objectid:	3338	Id:	182794
X coord:	396871	Y coord:	3965733
Db file nb:	RG 20516		
Use:	MUNICIPAL - CITY OR COUNTY SUPPLIED WATER		
Diversion:	10000	Pod rec nb:	182794
Well numbe:	RG 20516 EXPL (S-9)	Tws:	19N
Rng:	08E	Sec:	31
Q:	3	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	396921	Northing:	3965530
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	9		
Objectid:	1925	Id:	38207
X coord:	396570	Y coord:	3965639
Db file nb:	RG 00439		
Use:	72-12-1 LIVESTOCK WATERING		
Diversion:	3	Pod rec nb:	38207
Well numbe:	RG 00439	Tws:	19N
Rng:	07E	Sec:	36
Q:	4	Q2:	4
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	396620	Northing:	3965436
Start date:	19470808	Finish dat:	0
Depth well:	325	Depth wate:	0

Map ID:	10		
Objectid:	12993	Id:	176489
X coord:	398457	Y coord:	3965516
Db file nb:	RG 77270		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	176489
Well numbe:	RG 77270	Tws:	19N
Rng:	08E	Sec:	32
Q:	3	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	398507	Northing:	3965313
Start date:	0	Finish dat:	0
Depth well:	300	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	11		
Objectid:	3507	Id:	24388
X coord:	396664	Y coord:	3965135
Db file nb:	RG 22622		
Use:	OBSERVATION		
Diversion:	0	Pod rec nb:	24388
Well numbe:	RG 22622	Tws:	18N
Rng:	07E	Sec:	1
Q:	2	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	396714	Northing:	3964932
Start date:	19720719	Finish dat:	19720817
Depth well:	957	Depth wate:	0

Map ID:	13		
Objectid:	3371	Id:	40621
X coord:	396655	Y coord:	3964531
Db file nb:	RG 20937		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	40621
Well numbe:	RG 20937 EXPL	Tws:	18N
Rng:	07E	Sec:	1
Q:	4	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	396705	Northing:	3964328
Start date:	19720430	Finish dat:	19720623
Depth well:	1160	Depth wate:	105

Map ID:	15		
Objectid:	4469	Id:	5766
X coord:	397154	Y coord:	3964185
Db file nb:	RG 29550		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	5766
Well numbe:	RG 29550	Tws:	18N
Rng:	08E	Sec:	6
Q:	3	Q2:	0
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	397204	Northing:	3963982
Start date:	19771025	Finish dat:	19771026
Depth well:	675	Depth wate:	535

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	17		
Objectid:	3339	Id:	174248
X coord:	396552	Y coord:	3964029
Db file nb:	RG 20516		
Use:	MUNICIPAL - CITY OR COUNTY SUPPLIED WATER		
Diversion:	10000	Pod rec nb:	174248
Well numbe:	RG 20516 S-4	Tws:	18N
Rng:	07E	Sec:	1
Q:	4	Q2:	4
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	396602	Northing:	3963826
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	18		
Objectid:	1923	Id:	69136
X coord:	399329	Y coord:	3961944
Db file nb:	RG 00438		
Use:	72-12-1 LIVESTOCK WATERING		
Diversion:	3	Pod rec nb:	69136
Well numbe:	RG 00438	Tws:	18N
Rng:	08E	Sec:	17
Q:	2	Q2:	1
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	399379	Northing:	3961741
Start date:	19620606	Finish dat:	19620630
Depth well:	310	Depth wate:	220

Map ID:	18		
Objectid:	1924	Id:	24480
X coord:	399329	Y coord:	3961944
Db file nb:	RG 00438		
Use:	72-12-1 LIVESTOCK WATERING		
Diversion:	3	Pod rec nb:	24480
Well numbe:	RG 00438 DCL	Tws:	18N
Rng:	08E	Sec:	17
Q:	2	Q2:	1
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	399379	Northing:	3961741
Start date:	19360101	Finish dat:	0
Depth well:	390	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	20		
Objectid:	9425	Id:	69664
X coord:	403778	Y coord:	3955554
Db file nb:	RG 59973		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	69664
Well numbe:	RG 59973	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403828	Northing:	3955351
Start date:	19940801	Finish dat:	19940810
Depth well:	750	Depth wate:	540

Map ID:	21		
Objectid:	10491	Id:	35145
X coord:	403376	Y coord:	3955558
Db file nb:	RG 65584		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	35145
Well numbe:	RG 65584	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	1
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403426	Northing:	3955355
Start date:	19970813	Finish dat:	19970817
Depth well:	755	Depth wate:	535

Map ID:	21		
Objectid:	12509	Id:	163070
X coord:	403376	Y coord:	3955558
Db file nb:	RG 75069		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	163070
Well numbe:	RG 75069	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	1
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403426	Northing:	3955355
Start date:	20010927	Finish dat:	20011004
Depth well:	735	Depth wate:	500

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	22		
Objectid:	12444	Id:	168404
X coord:	403176	Y coord:	3955558
Db file nb:	RG 74811		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	168404
Well numbe:	RG 74811	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403226	Northing:	3955355
Start date:	20001215	Finish dat:	20010108
Depth well:	860	Depth wate:	427

Map ID:	23		
Objectid:	95897	Id:	16632
X coord:	401753	Y coord:	3955410
Db file nb:	RG 23626		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	16632
Well numbe:	RG 23626	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	548700	Y:	1723800
Easting:	0	Northing:	0
Start date:	19730701	Finish dat:	19730701
Depth well:	76	Depth wate:	50

Map ID:	24		
Objectid:	8610	Id:	39358
X coord:	403778	Y coord:	3955354
Db file nb:	RG 55734		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	39358
Well numbe:	RG 55734	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403828	Northing:	3955151
Start date:	19920814	Finish dat:	19920819
Depth well:	740	Depth wate:	500

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	25		
Objectid:	8326	Id:	2628
X coord:	404381	Y coord:	3955347
Db file nb:	RG 54262		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	2628
Well numbe:	RG 54262	Tws:	17N
Rng:	08E	Sec:	2
Q:	2	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404431	Northing:	3955144
Start date:	19910926	Finish dat:	19911108
Depth well:	755	Depth wate:	535

Map ID:	26		
Objectid:	8290	Id:	12917
X coord:	403775	Y coord:	3955152
Db file nb:	RG 54066		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	12917
Well numbe:	RG 54066	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403825	Northing:	3954949
Start date:	19910729	Finish dat:	19910731
Depth well:	760	Depth wate:	540

Map ID:	27		
Objectid:	11759	Id:	149037
X coord:	403575	Y coord:	3955152
Db file nb:	RG 71728		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	149037
Well numbe:	RG 71728	Tws:	17N
Rng:	08E	Sec:	2
Q:	1	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403625	Northing:	3954949
Start date:	19990419	Finish dat:	19990421
Depth well:	750	Depth wate:	485

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	28		
Objectid:	11395	Id:	143567
X coord:	403976	Y coord:	3954948
Db file nb:	RG 69782		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	143567
Well numbe:	RG 69782	Tws:	17N
Rng:	08E	Sec:	2
Q:	2	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404026	Northing:	3954745
Start date:	19980610	Finish dat:	19980613
Depth well:	785	Depth wate:	572

Map ID:	29		
Objectid:	10251	Id:	41570
X coord:	404374	Y coord:	3954742
Db file nb:	RG 64419		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	41570
Well numbe:	RG 64419	Tws:	17N
Rng:	08E	Sec:	2
Q:	4	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404424	Northing:	3954539
Start date:	19960524	Finish dat:	19960531
Depth well:	740	Depth wate:	500

Map ID:	29		
Objectid:	10489	Id:	23887
X coord:	404374	Y coord:	3954742
Db file nb:	RG 65566		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	23887
Well numbe:	RG 65566	Tws:	17N
Rng:	08E	Sec:	2
Q:	4	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404424	Northing:	3954539
Start date:	19980429	Finish dat:	19980505
Depth well:	765	Depth wate:	542

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	29		
Objectid:	3034	Id:	41410
X coord:	404475	Y coord:	3954643
Db file nb:	RG 17411		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	0	Pod rec nb:	41410
Well numbe:	RG 17411	Tws:	17N
Rng:	08E	Sec:	2
Q:	4	Q2:	2
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404525	Northing:	3954440
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	30		
Objectid:	11762	Id:	150355
X coord:	404026	Y coord:	3950622
Db file nb:	RG 71748		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	150355
Well numbe:	RG 71748	Tws:	17N
Rng:	08E	Sec:	23
Q:	2	Q2:	1
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404076	Northing:	3950419
Start date:	19990406	Finish dat:	19990413
Depth well:	854	Depth wate:	407

Map ID:	31		
Objectid:	12515	Id:	163696
X coord:	404120	Y coord:	3950319
Db file nb:	RG 75084		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	163696
Well numbe:	RG 75084	Tws:	17N
Rng:	08E	Sec:	23
Q:	2	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404170	Northing:	3950116
Start date:	20001130	Finish dat:	20001204
Depth well:	700	Depth wate:	390

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	31		
Objectid:	12470	Id:	164577
X coord:	404120	Y coord:	3950319
Db file nb:	RG 74926		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	164577
Well numbe:	RG 74926	Tws:	17N
Rng:	08E	Sec:	23
Q:	2	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404170	Northing:	3950116
Start date:	20001205	Finish dat:	20001208
Depth well:	700	Depth wate:	387

Map ID:	31		
Objectid:	12555	Id:	164643
X coord:	404120	Y coord:	3950319
Db file nb:	RG 75236		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	164643
Well numbe:	RG 75236	Tws:	17N
Rng:	08E	Sec:	23
Q:	2	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404170	Northing:	3950116
Start date:	20010307	Finish dat:	20010310
Depth well:	700	Depth wate:	387

Map ID:	32		
Objectid:	12408	Id:	161091
X coord:	403118	Y coord:	3950329
Db file nb:	RG 74646		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	161091
Well numbe:	RG 74646	Tws:	17N
Rng:	08E	Sec:	23
Q:	1	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403168	Northing:	3950126
Start date:	20000830	Finish dat:	20000902
Depth well:	600	Depth wate:	400

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	33		
Objectid:	12043	Id:	152517
X coord:	403214	Y coord:	3949828
Db file nb:	RG 72864		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	152517
Well numbe:	RG 72864	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403264	Northing:	3949625
Start date:	19991115	Finish dat:	19991116
Depth well:	600	Depth wate:	396

Map ID:	33		
Objectid:	12044	Id:	152518
X coord:	403214	Y coord:	3949828
Db file nb:	RG 72865		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	152518
Well numbe:	RG 72865	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403264	Northing:	3949625
Start date:	19990923	Finish dat:	19990930
Depth well:	800	Depth wate:	244

Map ID:	33		
Objectid:	11903	Id:	150651
X coord:	403214	Y coord:	3949828
Db file nb:	RG 72317		
Use:	Not Reported		
Diversion:	3	Pod rec nb:	150651
Well numbe:	RG 72317	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403264	Northing:	3949625
Start date:	19990920	Finish dat:	19990928
Depth well:	802	Depth wate:	244

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	33		
Objectid:	12864	Id:	173294
X coord:	403313	Y coord:	3949727
Db file nb:	RG 76696		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	173294
Well numbe:	RG 76696	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403363	Northing:	3949524
Start date:	20011119	Finish dat:	20011120
Depth well:	560	Depth wate:	395

Map ID:	33		
Objectid:	13068	Id:	177863
X coord:	403313	Y coord:	3949727
Db file nb:	RG 77644		
Use:	Not Reported		
Diversion:	3	Pod rec nb:	177863
Well numbe:	RG 77644	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403363	Northing:	3949524
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	33		
Objectid:	12045	Id:	152516
X coord:	403113	Y coord:	3949727
Db file nb:	RG 72866		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	152516
Well numbe:	RG 72866	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403163	Northing:	3949524
Start date:	20010413	Finish dat:	20010416
Depth well:	600	Depth wate:	33

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	34		
Objectid:	12378	Id:	160612
X coord:	403309	Y coord:	3949525
Db file nb:	RG 74556		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	160612
Well numbe:	RG 74556	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403359	Northing:	3949322
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	35		
Objectid:	12430	Id:	161511
X coord:	403109	Y coord:	3949525
Db file nb:	RG 74741		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	161511
Well numbe:	RG 74741	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403159	Northing:	3949322
Start date:	20000918	Finish dat:	20000921
Depth well:	700	Depth wate:	347

Map ID:	36		
Objectid:	12429	Id:	161513
X coord:	403109	Y coord:	3949325
Db file nb:	RG 74740		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	161513
Well numbe:	RG 74740	Tws:	17N
Rng:	08E	Sec:	23
Q:	3	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403159	Northing:	3949122
Start date:	20000922	Finish dat:	20000926
Depth well:	600	Depth wate:	347

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	37		
Objectid:	13147	Id:	178829
X coord:	403912	Y coord:	3949315
Db file nb:	RG 77954		
Use:	72-12-1 LIVESTOCK WATERING		
Diversion:	3	Pod rec nb:	178829
Well numbe:	RG 77954	Tws:	17N
Rng:	08E	Sec:	23
Q:	4	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403962	Northing:	3949112
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	38		
Objectid:	10711	Id:	23162
X coord:	404107	Y coord:	3949113
Db file nb:	RG 66570		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	23162
Well numbe:	RG 66570	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	1
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404157	Northing:	3948910
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	39		
Objectid:	10719	Id:	66397
X coord:	403705	Y coord:	3949117
Db file nb:	RG 66581		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	66397
Well numbe:	RG 66581	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403755	Northing:	3948914
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	40	Id:	23388
Objectid:	10432	Y coord:	3949108
X coord:	404508		
Db file nb:	RG 65277		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	23388
Well numbe:	RG 65277	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404558	Northing:	3948905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	40	Id:	13716
Objectid:	10748	Y coord:	3949108
X coord:	404508		
Db file nb:	RG 66624		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	13716
Well numbe:	RG 66624	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404558	Northing:	3948905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	40	Id:	18889
Objectid:	10747	Y coord:	3949108
X coord:	404508		
Db file nb:	RG 66623		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	18889
Well numbe:	RG 66623	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404558	Northing:	3948905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	41		
Objectid:	10825	Id:	130248
X coord:	403103	Y coord:	3949122
Db file nb:	RG 66978		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	130248
Well numbe:	RG 66978	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403153	Northing:	3948919
Start date:	19970428	Finish dat:	19970501
Depth well:	890	Depth wate:	240

Map ID:	42		
Objectid:	10708	Id:	19343
X coord:	403907	Y coord:	3949113
Db file nb:	RG 66566		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	19343
Well numbe:	RG 66566	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403957	Northing:	3948910
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	43		
Objectid:	10721	Id:	3528
X coord:	403505	Y coord:	3949117
Db file nb:	RG 66583		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	3528
Well numbe:	RG 66583	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403555	Northing:	3948914
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	44		
Objectid:	10284	Id:	29793
X coord:	404709	Y coord:	3949104
Db file nb:	RG 64583		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	29793
Well numbe:	RG 64583	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404759	Northing:	3948901
Start date:	19970410	Finish dat:	19970414
Depth well:	504	Depth wate:	397

Map ID:	44		
Objectid:	11219	Id:	140243
X coord:	404709	Y coord:	3949104
Db file nb:	RG 68837		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	140243
Well numbe:	RG 68837	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404759	Northing:	3948901
Start date:	19980331	Finish dat:	19980410
Depth well:	500	Depth wate:	394

Map ID:	45		
Objectid:	10706	Id:	9450
X coord:	404308	Y coord:	3949108
Db file nb:	RG 66564		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	9450
Well numbe:	RG 66564	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404358	Northing:	3948905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	46		
Objectid:	3273	Id:	18906
X coord:	403303	Y coord:	3948922
Db file nb:	RG 19951		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	18906
Well numbe:	RG 19951	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403353	Northing:	3948719
Start date:	19711227	Finish dat:	19720426
Depth well:	425	Depth wate:	403

Map ID:	47		
Objectid:	10710	Id:	17787
X coord:	404107	Y coord:	3948913
Db file nb:	RG 66568		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	17787
Well numbe:	RG 66568	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404157	Northing:	3948710
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	48		
Objectid:	10720	Id:	53680
X coord:	403705	Y coord:	3948917
Db file nb:	RG 66582		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	53680
Well numbe:	RG 66582	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403755	Northing:	3948714
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	49		
Objectid:	9546	Id:	25053
X coord:	404909	Y coord:	3948904
Db file nb:	RG 60791		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	25053
Well numbe:	RG 60791	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404959	Northing:	3948701
Start date:	19941106	Finish dat:	19941108
Depth well:	504	Depth wate:	367

Map ID:	50		
Objectid:	10707	Id:	67392
X coord:	404508	Y coord:	3948908
Db file nb:	RG 66565		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	67392
Well numbe:	RG 66565	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404558	Northing:	3948705
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	51		
Objectid:	10709	Id:	2881
X coord:	403907	Y coord:	3948913
Db file nb:	RG 66567		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	2881
Well numbe:	RG 66567	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403957	Northing:	3948710
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	52		
Objectid:	10431	Id:	16575
X coord:	403505	Y coord:	3948917
Db file nb:	RG 65276		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	16575
Well numbe:	RG 65276	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403555	Northing:	3948714
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	53		
Objectid:	10705	Id:	51837
X coord:	404308	Y coord:	3948908
Db file nb:	RG 66563		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	51837
Well numbe:	RG 66563	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404358	Northing:	3948705
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	54		
Objectid:	10714	Id:	9164
X coord:	404503	Y coord:	3948706
Db file nb:	RG 66576		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	9164
Well numbe:	RG 66576	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404553	Northing:	3948503
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	55		
Objectid:	10717	Id:	55326
X coord:	404101	Y coord:	3948710
Db file nb:	RG 66579		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	55326
Well numbe:	RG 66579	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404151	Northing:	3948507
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	56		
Objectid:	10726	Id:	62873
X coord:	403700	Y coord:	3948714
Db file nb:	RG 66599		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	62873
Well numbe:	RG 66599	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403750	Northing:	3948511
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	57		
Objectid:	10159	Id:	56917
X coord:	404905	Y coord:	3948701
Db file nb:	RG 63986		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	56917
Well numbe:	RG 63986	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404955	Northing:	3948498
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	57		
Objectid:	10158	Id:	14085
X coord:	404905	Y coord:	3948701
Db file nb:	RG 63985		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	14085
Well numbe:	RG 63985	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404955	Northing:	3948498
Start date:	19960501	Finish dat:	19960503
Depth well:	503	Depth wate:	360

Map ID:	58		
Objectid:	10715	Id:	38998
X coord:	404303	Y coord:	3948706
Db file nb:	RG 66577		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	38998
Well numbe:	RG 66577	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404353	Northing:	3948503
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	59		
Objectid:	10743	Id:	21567
X coord:	403901	Y coord:	3948710
Db file nb:	RG 66614		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	21567
Well numbe:	RG 66614	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403951	Northing:	3948507
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	60		
Objectid:	10724	Id:	10869
X coord:	403500	Y coord:	3948714
Db file nb:	RG 66597		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	10869
Well numbe:	RG 66597	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403550	Northing:	3948511
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	54		
Objectid:	11668	Id:	147198
X coord:	404705	Y coord:	3948701
Db file nb:	RG 71164		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	147198
Well numbe:	RG 71164	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404755	Northing:	3948498
Start date:	19990409	Finish dat:	19990414
Depth well:	500	Depth wate:	344

Map ID:	54		
Objectid:	2699	Id:	66817
X coord:	404705	Y coord:	3948701
Db file nb:	RG 12564		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	66817
Well numbe:	RG 12564	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404755	Northing:	3948498
Start date:	19650427	Finish dat:	19650511
Depth well:	400	Depth wate:	360

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	57		
Objectid:	107082	Id:	186730
X coord:	404889	Y coord:	3948694
Db file nb:	RG 79413		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	186730
Well numbe:	RG 79413	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	559269	Y:	1701895
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	600	Depth wate:	0

Map ID:	54		
Objectid:	101410	Id:	30152
X coord:	404639	Y coord:	3948684
Db file nb:	RG 64068		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	30152
Well numbe:	RG 64068	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	558450	Y:	1701850
Easting:	0	Northing:	0
Start date:	19960222	Finish dat:	19960223
Depth well:	265	Depth wate:	15

Map ID:	61		
Objectid:	97139	Id:	38886
X coord:	404500	Y coord:	3948518
Db file nb:	RG 35714		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	38886
Well numbe:	RG 35714	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558000	Y:	1701300
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	61		
Objectid:	10713	Id:	10948
X coord:	404503	Y coord:	3948506
Db file nb:	RG 66572		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	10948
Well numbe:	RG 66572	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404553	Northing:	3948303
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	62		
Objectid:	12394	Id:	160938
X coord:	404101	Y coord:	3948510
Db file nb:	RG 74598		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	160938
Well numbe:	RG 74598	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	3
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404151	Northing:	3948307
Start date:	20000906	Finish dat:	20001016
Depth well:	960	Depth wate:	360

Map ID:	62		
Objectid:	10718	Id:	42175
X coord:	404101	Y coord:	3948510
Db file nb:	RG 66580		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	42175
Well numbe:	RG 66580	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	3
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404151	Northing:	3948307
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	63		
Objectid:	10725	Id:	15108
X coord:	403700	Y coord:	3948514
Db file nb:	RG 66598		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	15108
Well numbe:	RG 66598	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403750	Northing:	3948311
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	64		
Objectid:	4587	Id:	58735
X coord:	404905	Y coord:	3948501
Db file nb:	RG 30297 X		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	58735
Well numbe:	RG 30297 X	Tws:	17N
Rng:	08E	Sec:	25
Q:	1	Q2:	3
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404955	Northing:	3948298
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	65		
Objectid:	10712	Id:	70082
X coord:	404303	Y coord:	3948506
Db file nb:	RG 66571		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	70082
Well numbe:	RG 66571	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	4
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404353	Northing:	3948303
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	66		
Objectid:	10716	Id:	31332
X coord:	403901	Y coord:	3948510
Db file nb:	RG 66578		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	31332
Well numbe:	RG 66578	Tws:	17N
Rng:	08E	Sec:	26
Q:	2	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403951	Northing:	3948307
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	67		
Objectid:	10722	Id:	53748
X coord:	403500	Y coord:	3948514
Db file nb:	RG 66584		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	53748
Well numbe:	RG 66584	Tws:	17N
Rng:	08E	Sec:	26
Q:	1	Q2:	4
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403550	Northing:	3948311
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	68		
Objectid:	10732	Id:	16938
X coord:	404096	Y coord:	3948308
Db file nb:	RG 66606		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	16938
Well numbe:	RG 66606	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	1
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404146	Northing:	3948105
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	69		
Objectid:	10434	Id:	62530
X coord:	403695	Y coord:	3948312
Db file nb:	RG 65279		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	62530
Well numbe:	RG 65279	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403745	Northing:	3948109
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	70		
Objectid:	10433	Id:	61536
X coord:	404498	Y coord:	3948303
Db file nb:	RG 65278		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	61536
Well numbe:	RG 65278	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404548	Northing:	3948100
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	71		
Objectid:	10731	Id:	51707
X coord:	403896	Y coord:	3948308
Db file nb:	RG 66605		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	51707
Well numbe:	RG 66605	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403946	Northing:	3948105
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	72		
Objectid:	3095	Id:	9957
X coord:	404701	Y coord:	3948299
Db file nb:	RG 18119		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	9957
Well numbe:	RG 18119	Tws:	17N
Rng:	08E	Sec:	25
Q:	3	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404751	Northing:	3948096
Start date:	19701220	Finish dat:	19710202
Depth well:	440	Depth wate:	340

Map ID:	73		
Objectid:	10734	Id:	42401
X coord:	403495	Y coord:	3948312
Db file nb:	RG 66608		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	42401
Well numbe:	RG 66608	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403545	Northing:	3948109
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	74		
Objectid:	10729	Id:	20908
X coord:	404298	Y coord:	3948303
Db file nb:	RG 66603		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	20908
Well numbe:	RG 66603	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	2
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404348	Northing:	3948100
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	75		
Objectid:	10730	Id:	49076
X coord:	404096	Y coord:	3948108
Db file nb:	RG 66604		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	49076
Well numbe:	RG 66604	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404146	Northing:	3947905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	76		
Objectid:	10735	Id:	21657
X coord:	403695	Y coord:	3948112
Db file nb:	RG 66609		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	21657
Well numbe:	RG 66609	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403745	Northing:	3947909
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	77		
Objectid:	10728	Id:	35818
X coord:	404498	Y coord:	3948103
Db file nb:	RG 66601		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	35818
Well numbe:	RG 66601	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	2
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404548	Northing:	3947900
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	78		
Objectid:	10733	Id:	13830
X coord:	403896	Y coord:	3948108
Db file nb:	RG 66607		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	13830
Well numbe:	RG 66607	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403946	Northing:	3947905
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	79		
Objectid:	9507	Id:	54508
X coord:	404701	Y coord:	3948099
Db file nb:	RG 60445		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	54508
Well numbe:	RG 60445	Tws:	17N
Rng:	08E	Sec:	25
Q:	3	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404751	Northing:	3947896
Start date:	19940909	Finish dat:	19940910
Depth well:	560	Depth wate:	300

Map ID:	80		
Objectid:	10736	Id:	3656
X coord:	403495	Y coord:	3948112
Db file nb:	RG 66610		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	3656
Well numbe:	RG 66610	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403545	Northing:	3947909
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	81		
Objectid:	10727	Id:	21576
X coord:	404298	Y coord:	3948103
Db file nb:	RG 66600		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	21576
Well numbe:	RG 66600	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404348	Northing:	3947900
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	82		
Objectid:	11650	Id:	147052
X coord:	402583	Y coord:	3948024
Db file nb:	RG 71098		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	147052
Well numbe:	RG 71098	Tws:	17N
Rng:	08E	Sec:	27
Q:	4	Q2:	0
Q3:	Not Reported	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	402633	Northing:	3947821
Start date:	20000517	Finish dat:	20000526
Depth well:	370	Depth wate:	291

Map ID:	83		
Objectid:	10701	Id:	24380
X coord:	404091	Y coord:	3947906
Db file nb:	RG 66559		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	24380
Well numbe:	RG 66559	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404141	Northing:	3947703
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	83		
Objectid:	10702	Id:	35859
X coord:	404091	Y coord:	3947906
Db file nb:	RG 66560		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	35859
Well numbe:	RG 66560	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404141	Northing:	3947703
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	84		
Objectid:	10699	Id:	55346
X coord:	403689	Y coord:	3947910
Db file nb:	RG 66557		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	55346
Well numbe:	RG 66557	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403739	Northing:	3947707
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	84		
Objectid:	10700	Id:	24099
X coord:	403689	Y coord:	3947910
Db file nb:	RG 66558		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	24099
Well numbe:	RG 66558	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403739	Northing:	3947707
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	85		
Objectid:	13000	Id:	179066
X coord:	404896	Y coord:	3947897
Db file nb:	Not Reported		
Use:	Not Reported		
Diversion:	0	Pod rec nb:	179066
Well numbe:	RG 77301 CLW231047	Tws:	17N
Rng:	08E	Sec:	25
Q:	3	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404946	Northing:	3947694
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	85		
Objectid:	12999	Id:	176529
X coord:	404896	Y coord:	3947897
Db file nb:	RG 77301		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	176529
Well numbe:	RG 77301	Tws:	17N
Rng:	08E	Sec:	25
Q:	3	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404946	Northing:	3947694
Start date:	20020524	Finish dat:	20020528
Depth well:	550	Depth wate:	309

Map ID:	86		
Objectid:	10742	Id:	4187
X coord:	404494	Y coord:	3947901
Db file nb:	RG 66613		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	4187
Well numbe:	RG 66613	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404544	Northing:	3947698
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	87		
Objectid:	10703	Id:	36600
X coord:	403891	Y coord:	3947906
Db file nb:	RG 66561		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	36600
Well numbe:	RG 66561	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403941	Northing:	3947703
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	87		
Objectid:	10704	Id:	56799
X coord:	403891	Y coord:	3947906
Db file nb:	RG 66562		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	56799
Well numbe:	RG 66562	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403941	Northing:	3947703
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	88		
Objectid:	10697	Id:	17810
X coord:	403489	Y coord:	3947910
Db file nb:	RG 66555		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	17810
Well numbe:	RG 66555	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403539	Northing:	3947707
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	88		
Objectid:	10698	Id:	61111
X coord:	403489	Y coord:	3947910
Db file nb:	RG 66556		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	61111
Well numbe:	RG 66556	Tws:	17N
Rng:	08E	Sec:	26
Q:	3	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403539	Northing:	3947707
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	89		
Objectid:	10741	Id:	18257
X coord:	404294	Y coord:	3947901
Db file nb:	RG 66612		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	18257
Well numbe:	RG 66612	Tws:	17N
Rng:	08E	Sec:	26
Q:	4	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404344	Northing:	3947698
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	90		
Objectid:	9579	Id:	36278
X coord:	404696	Y coord:	3947697
Db file nb:	RG 60962		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	36278
Well numbe:	RG 60962	Tws:	17N
Rng:	08E	Sec:	25
Q:	3	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404746	Northing:	3947494
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	91		
Objectid:	10826	Id:	176311
X coord:	403685	Y coord:	3947508
Db file nb:	RG 66978		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	176311
Well numbe:	RG 66978 S	Tws:	17N
Rng:	08E	Sec:	35
Q:	1	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403735	Northing:	3947305
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	91		
Objectid:	11750	Id:	148931
X coord:	403685	Y coord:	3947508
Db file nb:	RG 71685		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	148931
Well numbe:	RG 71685	Tws:	17N
Rng:	08E	Sec:	35
Q:	1	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	403735	Northing:	3947305
Start date:	19990330	Finish dat:	19990403
Depth well:	700	Depth wate:	260

Map ID:	92		
Objectid:	10420	Id:	12294
X coord:	402074	Y coord:	3947523
Db file nb:	RG 65245		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	12294
Well numbe:	RG 65245	Tws:	17N
Rng:	08E	Sec:	34
Q:	1	Q2:	2
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	402124	Northing:	3947320
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	93		
Objectid:	96668	Id:	26129
X coord:	402872	Y coord:	3947503
Db file nb:	RG 31566 REPAR		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	26129
Well numbe:	RG 31566	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	552700	Y:	1697900
Easting:	0	Northing:	0
Start date:	19781101	Finish dat:	19781101
Depth well:	125	Depth wate:	60

Map ID:	94		
Objectid:	6675	Id:	7158
X coord:	404892	Y coord:	3947295
Db file nb:	RG 43351		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	7158
Well numbe:	RG 43351	Tws:	17N
Rng:	08E	Sec:	36
Q:	1	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404942	Northing:	3947092
Start date:	19910917	Finish dat:	19910923
Depth well:	373	Depth wate:	0

Map ID:	94		
Objectid:	10590	Id:	47874
X coord:	404892	Y coord:	3947295
Db file nb:	RG 66047		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	47874
Well numbe:	RG 66047	Tws:	17N
Rng:	08E	Sec:	36
Q:	1	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404942	Northing:	3947092
Start date:	19960927	Finish dat:	19961001
Depth well:	450	Depth wate:	250

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	95		
Objectid:	5032	Id:	58518
X coord:	405094	Y coord:	3947289
Db file nb:	RG 33103		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	58518
Well numbe:	RG 33103	Tws:	17N
Rng:	08E	Sec:	36
Q:	1	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405144	Northing:	3947086
Start date:	19790906	Finish dat:	19790914
Depth well:	360	Depth wate:	305

Map ID:	95		
Objectid:	10799	Id:	25380
X coord:	405094	Y coord:	3947289
Db file nb:	RG 66888		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	25380
Well numbe:	RG 66888	Tws:	17N
Rng:	08E	Sec:	36
Q:	1	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405144	Northing:	3947086
Start date:	19980420	Finish dat:	19980424
Depth well:	440	Depth wate:	309

Map ID:	96		
Objectid:	11802	Id:	149669
X coord:	405090	Y coord:	3947087
Db file nb:	RG 71945		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	149669
Well numbe:	RG 71945	Tws:	17N
Rng:	08E	Sec:	36
Q:	1	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405140	Northing:	3946884
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	97		
Objectid:	4667	Id:	21121
X coord:	405594	Y coord:	3946983
Db file nb:	RG 30777		
Use:	NO USE OF RIGHT OR POD		
Diversion:	0	Pod rec nb:	21121
Well numbe:	RG 30777	Tws:	17N
Rng:	08E	Sec:	36
Q:	2	Q2:	3
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405644	Northing:	3946780
Start date:	19780707	Finish dat:	19780715
Depth well:	663	Depth wate:	355

Map ID:	97		
Objectid:	4667	Id:	21121
X coord:	405594	Y coord:	3946983
Db file nb:	RG 30777 EXPL		
Use:	OBSERVATION		
Diversion:	3	Pod rec nb:	21121
Well numbe:	RG 30777	Tws:	17N
Rng:	08E	Sec:	36
Q:	2	Q2:	3
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405644	Northing:	3946780
Start date:	19780707	Finish dat:	19780715
Depth well:	663	Depth wate:	355

Map ID:	98		
Objectid:	5855	Id:	5377
X coord:	405383	Y coord:	3946792
Db file nb:	RG 38107		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	5377
Well numbe:	RG 38107	Tws:	17N
Rng:	08E	Sec:	36
Q:	0	Q2:	0
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405433	Northing:	3946589
Start date:	19820622	Finish dat:	19820624
Depth well:	520	Depth wate:	370

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	98		
Objectid:	4538	Id:	50753
X coord:	405383	Y coord:	3946792
Db file nb:	RG 29955		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	50753
Well numbe:	RG 29955	Tws:	17N
Rng:	08E	Sec:	36
Q:	0	Q2:	0
Q3:	0	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405433	Northing:	3946589
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	98		
Objectid:	11941	Id:	150988
X coord:	405489	Y coord:	3946681
Db file nb:	RG 72432		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	150988
Well numbe:	RG 72432	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405539	Northing:	3946478
Start date:	19991018	Finish dat:	19991021
Depth well:	440	Depth wate:	315

Map ID:	98		
Objectid:	9771	Id:	7094
X coord:	405489	Y coord:	3946681
Db file nb:	RG 61734		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	7094
Well numbe:	RG 61734	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405539	Northing:	3946478
Start date:	19950215	Finish dat:	19950215
Depth well:	650	Depth wate:	330

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	98		
Objectid:	12498	Id:	163433
X coord:	405489	Y coord:	3946681
Db file nb:	RG 75040		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	163433
Well numbe:	RG 75040	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	1
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405539	Northing:	3946478
Start date:	20010410	Finish dat:	20010417
Depth well:	500	Depth wate:	315

Map ID:	99		
Objectid:	12994	Id:	176411
X coord:	404079	Y coord:	3946500
Db file nb:	RG 77280		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	176411
Well numbe:	RG 77280	Tws:	17N
Rng:	08E	Sec:	35
Q:	4	Q2:	1
Q3:	4	Zone:	C
X:	556000	Y:	1694500
Easting:	404129	Northing:	3946297
Start date:	20020315	Finish dat:	20020330
Depth well:	735	Depth wate:	282

Map ID:	100		
Objectid:	13374	Id:	182807
X coord:	404884	Y coord:	3946490
Db file nb:	RG 78964		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	182807
Well numbe:	RG 78964	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	1
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404934	Northing:	3946287
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	101		
Objectid:	8917	Id:	3847
X coord:	405086	Y coord:	3946486
Db file nb:	RG 57248		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	3847
Well numbe:	RG 57248	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405136	Northing:	3946283
Start date:	19930526	Finish dat:	19930607
Depth well:	500	Depth wate:	400

Map ID:	101		
Objectid:	6552	Id:	19651
X coord:	405086	Y coord:	3946486
Db file nb:	RG 42411		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	19651
Well numbe:	RG 42411	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	2
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405136	Northing:	3946283
Start date:	19840815	Finish dat:	19840817
Depth well:	440	Depth wate:	320

Map ID:	102		
Objectid:	12130	Id:	155205
X coord:	405489	Y coord:	3946481
Db file nb:	RG 73380		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	155205
Well numbe:	RG 73380	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405539	Northing:	3946278
Start date:	20000126	Finish dat:	20000202
Depth well:	480	Depth wate:	348

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	102		
Objectid:	9127	Id:	50847
X coord:	405489	Y coord:	3946481
Db file nb:	RG 58259		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	50847
Well numbe:	RG 58259	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	1
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405539	Northing:	3946278
Start date:	19931026	Finish dat:	19931030
Depth well:	500	Depth wate:	200

Map ID:	103		
Objectid:	97947	Id:	21776
X coord:	403039	Y coord:	3946312
Db file nb:	RG 42844		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	21776
Well numbe:	RG 42844	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	553300	Y:	1694000
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	104		
Objectid:	12207	Id:	156762
X coord:	405282	Y coord:	3946284
Db file nb:	RG 73721		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	156762
Well numbe:	RG 73721	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405332	Northing:	3946081
Start date:	20000503	Finish dat:	20000510
Depth well:	520	Depth wate:	319

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	105		
Objectid:	6479	Id:	30959
X coord:	404879	Y coord:	3946288
Db file nb:	RG 41819		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	30959
Well numbe:	RG 41819	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404929	Northing:	3946085
Start date:	19840514	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	106		
Objectid:	12623	Id:	169039
X coord:	405685	Y coord:	3946279
Db file nb:	RG 75590		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	169039
Well numbe:	RG 75590	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	3
Q3:	2	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405735	Northing:	3946076
Start date:	20010710	Finish dat:	20010716
Depth well:	440	Depth wate:	317

Map ID:	107		
Objectid:	12755	Id:	171427
X coord:	405082	Y coord:	3946284
Db file nb:	RG 76184		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	171427
Well numbe:	RG 76184	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405132	Northing:	3946081
Start date:	20010719	Finish dat:	20010725
Depth well:	500	Depth wate:	307

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	107		
Objectid:	11694	Id:	147498
X coord:	405082	Y coord:	3946284
Db file nb:	RG 71293		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	147498
Well numbe:	RG 71293	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405132	Northing:	3946081
Start date:	19990212	Finish dat:	19990219
Depth well:	520	Depth wate:	300

Map ID:	107		
Objectid:	12624	Id:	169019
X coord:	405082	Y coord:	3946284
Db file nb:	RG 75592		
Use:	72-12-1 MULTIPLE DOMESTIC HOUSEHOLDS		
Diversion:	3	Pod rec nb:	169019
Well numbe:	RG 75592	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405132	Northing:	3946081
Start date:	20010325	Finish dat:	20010402
Depth well:	520	Depth wate:	322

Map ID:	108		
Objectid:	13146	Id:	178816
X coord:	402667	Y coord:	3946310
Db file nb:	RG 77953		
Use:	72-12-1 LIVESTOCK WATERING		
Diversion:	3	Pod rec nb:	178816
Well numbe:	RG 77953	Tws:	17N
Rng:	08E	Sec:	34
Q:	4	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	402717	Northing:	3946107
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	109		
Objectid:	6526	Id:	43756
X coord:	404679	Y coord:	3946288
Db file nb:	RG 42173		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	43756
Well numbe:	RG 42173	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	404729	Northing:	3946085
Start date:	19840716	Finish dat:	19840726
Depth well:	440	Depth wate:	320

Map ID:	110		
Objectid:	10754	Id:	17351
X coord:	405485	Y coord:	3946279
Db file nb:	RG 66643		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	17351
Well numbe:	RG 66643	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	3
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405535	Northing:	3946076
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	111		
Objectid:	5383	Id:	58274
X coord:	405888	Y coord:	3946274
Db file nb:	RG 35097		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	58274
Well numbe:	RG 35097	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	4
Q3:	1	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405938	Northing:	3946071
Start date:	19800926	Finish dat:	19801003
Depth well:	345	Depth wate:	305

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	112		
Objectid:	12629	Id:	169104
X coord:	405282	Y coord:	3946084
Db file nb:	RG 75612		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	169104
Well numbe:	RG 75612	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405332	Northing:	3945881
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	112		
Objectid:	12211	Id:	156809
X coord:	405282	Y coord:	3946084
Db file nb:	RG 73727		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	156809
Well numbe:	RG 73727	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405332	Northing:	3945881
Start date:	20000526	Finish dat:	20000605
Depth well:	520	Depth wate:	310

Map ID:	112		
Objectid:	8363	Id:	46916
X coord:	405282	Y coord:	3946084
Db file nb:	RG 54392		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	46916
Well numbe:	RG 54392	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405332	Northing:	3945881
Start date:	19911112	Finish dat:	19911114
Depth well:	500	Depth wate:	330

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	113		
Objectid:	11980	Id:	151238
X coord:	405685	Y coord:	3946079
Db file nb:	RG 72585		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	151238
Well numbe:	RG 72585	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	3
Q3:	4	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405735	Northing:	3945876
Start date:	19990917	Finish dat:	19990917
Depth well:	480	Depth wate:	460

Map ID:	114		
Objectid:	13410	Id:	183624
X coord:	405082	Y coord:	3946084
Db file nb:	RG 79119		
Use:	Not Reported		
Diversion:	3	Pod rec nb:	183624
Well numbe:	RG 79119	Tws:	17N
Rng:	08E	Sec:	36
Q:	3	Q2:	4
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405132	Northing:	3945881
Start date:	20021019	Finish dat:	20021021
Depth well:	500	Depth wate:	296

Map ID:	115		
Objectid:	10753	Id:	30354
X coord:	405485	Y coord:	3946079
Db file nb:	RG 66642		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	30354
Well numbe:	RG 66642	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405535	Northing:	3945876
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	115		
Objectid:	12221	Id:	156761
X coord:	405485	Y coord:	3946079
Db file nb:	RG 73789		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	156761
Well numbe:	RG 73789	Tws:	17N
Rng:	08E	Sec:	36
Q:	4	Q2:	3
Q3:	3	Zone:	Not Reported
X:	Not Reported	Y:	Not Reported
Easting:	405535	Northing:	3945876
Start date:	20000512	Finish dat:	20000515
Depth well:	450	Depth wate:	250

Map ID:	117		
Objectid:	99461	Id:	7971
X coord:	406285	Y coord:	3944869
Db file nb:	RG 55639		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	7971
Well numbe:	RG 55639	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	564010	Y:	1689400
Easting:	0	Northing:	0
Start date:	19920627	Finish dat:	19920630
Depth well:	440	Depth wate:	330

Map ID:	120		
Objectid:	97571	Id:	50241
X coord:	404661	Y coord:	3944432
Db file nb:	RG 39827		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	50241
Well numbe:	RG 39827	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558700	Y:	1687900
Easting:	0	Northing:	0
Start date:	19830510	Finish dat:	19830511
Depth well:	520	Depth wate:	320

GEOCHECK VERSION 2.1 **STATE DATABASE WELL INFORMATION**

Map ID:	120		
Objectid:	96567	Id:	6349
X coord:	404508	Y coord:	3944373
Db file nb:	RG 30898		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	6349
Well numbe:	RG 30898	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558200	Y:	1687700
Easting:	0	Northing:	0
Start date:	19780725	Finish dat:	19780726
Depth well:	510	Depth wate:	300

Map ID:	120		
Objectid:	96280	Id:	42342
X coord:	404386	Y coord:	3944344
Db file nb:	RG 27881		
Use:	AGRICULTURE OTHER THAN IRRIGATION		
Diversion:	10	Pod rec nb:	42342
Well numbe:	RG 27881	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	557800	Y:	1687600
Easting:	0	Northing:	0
Start date:	19761002	Finish dat:	19761004
Depth well:	365	Depth wate:	280

Map ID:	124		
Objectid:	96832	Id:	53215
X coord:	404536	Y coord:	3944159
Db file nb:	RG 33014		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	53215
Well numbe:	RG 33014	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558300	Y:	1687000
Easting:	0	Northing:	0
Start date:	19790811	Finish dat:	19790813
Depth well:	540	Depth wate:	245

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	125		
Objectid:	96694	Id:	4338
X coord:	404441	Y coord:	3943917
Db file nb:	RG 31790		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	4338
Well numbe:	RG 31790	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558000	Y:	1686200
Easting:	0	Northing:	0
Start date:	19790115	Finish dat:	19790116
Depth well:	500	Depth wate:	380

Map ID:	125		
Objectid:	96693	Id:	29079
X coord:	404441	Y coord:	3943856
Db file nb:	RG 31789		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	29079
Well numbe:	RG 31789	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	558000	Y:	1686000
Easting:	0	Northing:	0
Start date:	19790808	Finish dat:	19790809
Depth well:	600	Depth wate:	245

Map ID:	128		
Objectid:	95667	Id:	9174
X coord:	404801	Y coord:	3943464
Db file nb:	RG 20379		
Use:	IRRIGATION		
Diversion:	0	Pod rec nb:	9174
Well numbe:	RG 20379 -S	Tws:	16N
Rng:	08E	Sec:	12
Q:	3	Q2:	1
Q3:	2	Zone:	C
X:	559200	Y:	1684730
Easting:	0	Northing:	0
Start date:	19720923	Finish dat:	19721012
Depth well:	700	Depth wate:	276

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	129		
Objectid:	97570	Id:	43391
X coord:	407085	Y coord:	3943304
Db file nb:	RG 39820		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	0	Pod rec nb:	43391
Well numbe:	RG 39820	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	566700	Y:	1684300
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	131		
Objectid:	103919	Id:	150471
X coord:	403783	Y coord:	3941304
Db file nb:	RG 72310		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	150471
Well numbe:	RG 72310	Tws:	16N
Rng:	08E	Sec:	14
Q:	4	Q2:	3
Q3:	3	Zone:	C
X:	555950	Y:	1677600
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	0	Depth wate:	0

Map ID:	132		
Objectid:	100211	Id:	61238
X coord:	403645	Y coord:	3941184
Db file nb:	RG 59613		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	61238
Well numbe:	RG 59613	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	555500	Y:	1677200
Easting:	0	Northing:	0
Start date:	19940706	Finish dat:	19940706
Depth well:	304	Depth wate:	108

GEOCHECK VERSION 2.1

STATE DATABASE WELL INFORMATION

Map ID:	133	Id:	176222
Objectid:	105938	Y coord:	3939786
X coord:	403353		
Db file nb:	RG 77242		
Use:	72-12-1 SANITARY IN CONJUNCTION WITH A COMMERCIAL USE		
Diversion:	3	Pod rec nb:	176222
Well numbe:	RG 77242	Tws:	16N
Rng:	08E	Sec:	23
Q:	3	Q2:	4
Q3:	1	Zone:	C
X:	554600	Y:	1672600
Easting:	0	Northing:	0
Start date:	0	Finish dat:	0
Depth well:	1500	Depth wate:	0

Map ID:	134	Id:	69840
Objectid:	98983	Y coord:	3939195
X coord:	401882		
Db file nb:	RG 53159		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	69840
Well numbe:	RG 53159	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	Not Reported	Zone:	C
X:	549800	Y:	1670600
Easting:	0	Northing:	0
Start date:	19901121	Finish dat:	19901121
Depth well:	150	Depth wate:	70

Map ID:	134	Id:	44880
Objectid:	98285	Y coord:	3939195
X coord:	401882		
Db file nb:	RG 45965		
Use:	72-12-1 DOMESTIC ONE HOUSEHOLD		
Diversion:	3	Pod rec nb:	44880
Well numbe:	RG 45965	Tws:	Not Reported
Rng:	Not Reported	Sec:	0
Q:	0	Q2:	0
Q3:	0	Zone:	C
X:	549800	Y:	1670600
Easting:	0	Northing:	0
Start date:	19860818	Finish dat:	19860819
Depth well:	165	Depth wate:	100

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NM3505126 PWS Status: Not Reported
 Date Initiated: Not Reported Date Deactivated: Not Reported
 PWS Name: SANGRE DE CRISTO WATER COMPANY
 PO BOX 4670
 SANTA FE, NM 87502

Source: Surface water	
Treatment Objective: CORROSION CONTROL	Process: PH ADJUSTMENT, POST
Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED
Treatment Objective: OTHER	Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude:	35 39 32.0000	Facility Longitude:	105 57 54.0000
Facility Latitude:	35 40 21.0000	Facility Longitude:	105 58 48.0000
Facility Latitude:	35 40 33.0000	Facility Longitude:	105 57 43.0000
Facility Latitude:	35 40 41.0000	Facility Longitude:	105 58 15.0000
Facility Latitude:	35 41 4.0000	Facility Longitude:	105 58 0.0000
Facility Latitude:	35 41 9.0000	Facility Longitude:	105 57 37.0000
Facility Latitude:	35 41 18.0000	Facility Longitude:	105 57 25.0000
Facility Latitude:	35 48 54.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 8.0000	Facility Longitude:	106 8 44.0000
Facility Latitude:	35 49 13.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 46.0000	Facility Longitude:	106 9 20.0000
Facility Latitude:	35 49 53.0000	Facility Longitude:	106 9 55.0000
Facility Latitude:	35 50 5.0000	Facility Longitude:	106 9 28.0000
Facility Latitude:	35 50 6.0000	Facility Longitude:	106 9 3.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

PWS ID:	NM3505126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANGRE DE CRISTO WATER COMPANY		
	PO BOX 4670		
	SANTA FE, NM 87502		

Source: Surface water	
Treatment Objective: CORROSION CONTROL	Process: PH ADJUSTMENT, POST
Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED
Treatment Objective: OTHER	Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude:	35 39 32.0000	Facility Longitude:	105 57 54.0000
Facility Latitude:	35 40 21.0000	Facility Longitude:	105 58 48.0000
Facility Latitude:	35 40 33.0000	Facility Longitude:	105 57 43.0000
Facility Latitude:	35 40 41.0000	Facility Longitude:	105 58 15.0000
Facility Latitude:	35 41 4.0000	Facility Longitude:	105 58 0.0000
Facility Latitude:	35 41 9.0000	Facility Longitude:	105 57 37.0000
Facility Latitude:	35 41 18.0000	Facility Longitude:	105 57 25.0000
Facility Latitude:	35 48 54.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 8.0000	Facility Longitude:	106 8 44.0000
Facility Latitude:	35 49 13.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 46.0000	Facility Longitude:	106 9 20.0000
Facility Latitude:	35 49 53.0000	Facility Longitude:	106 9 55.0000
Facility Latitude:	35 50 5.0000	Facility Longitude:	106 9 28.0000
Facility Latitude:	35 50 6.0000	Facility Longitude:	106 9 3.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

PWS ID:	NM3505126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANGRE DE CRISTO WATER COMPANY		
	PO BOX 4670		
	SANTA FE, NM 87502		

Source: Surface water	
Treatment Objective: CORROSION CONTROL	Process: PH ADJUSTMENT, POST
Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED
Treatment Objective: OTHER	Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude:	35 39 32.0000	Facility Longitude:	105 57 54.0000
Facility Latitude:	35 40 21.0000	Facility Longitude:	105 58 48.0000
Facility Latitude:	35 40 33.0000	Facility Longitude:	105 57 43.0000
Facility Latitude:	35 40 41.0000	Facility Longitude:	105 58 15.0000
Facility Latitude:	35 41 4.0000	Facility Longitude:	105 58 0.0000
Facility Latitude:	35 41 9.0000	Facility Longitude:	105 57 37.0000
Facility Latitude:	35 41 18.0000	Facility Longitude:	105 57 25.0000
Facility Latitude:	35 48 54.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 8.0000	Facility Longitude:	106 8 44.0000
Facility Latitude:	35 49 13.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 46.0000	Facility Longitude:	106 9 20.0000
Facility Latitude:	35 49 53.0000	Facility Longitude:	106 9 55.0000
Facility Latitude:	35 50 5.0000	Facility Longitude:	106 9 28.0000
Facility Latitude:	35 50 6.0000	Facility Longitude:	106 9 3.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

PWS ID:	NM3505126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANGRE DE CRISTO WATER COMPANY		
	PO BOX 4670		
	SANTA FE, NM 87502		

Source: Surface water	
Treatment Objective: CORROSION CONTROL	Process: PH ADJUSTMENT, POST
Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED
Treatment Objective: OTHER	Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude:	35 39 32.0000	Facility Longitude:	105 57 54.0000
Facility Latitude:	35 40 21.0000	Facility Longitude:	105 58 48.0000
Facility Latitude:	35 40 33.0000	Facility Longitude:	105 57 43.0000
Facility Latitude:	35 40 41.0000	Facility Longitude:	105 58 15.0000
Facility Latitude:	35 41 4.0000	Facility Longitude:	105 58 0.0000
Facility Latitude:	35 41 9.0000	Facility Longitude:	105 57 37.0000
Facility Latitude:	35 41 18.0000	Facility Longitude:	105 57 25.0000
Facility Latitude:	35 48 54.0000	Facility Longitude:	106 8 53.0000

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Facility Latitude:	35 49 8.0000	Facility Longitude:	106 8 44.0000
Facility Latitude:	35 49 13.0000	Facility Longitude:	106 8 53.0000
Facility Latitude:	35 49 46.0000	Facility Longitude:	106 9 20.0000
Facility Latitude:	35 49 53.0000	Facility Longitude:	106 9 55.0000
Facility Latitude:	35 50 5.0000	Facility Longitude:	106 9 28.0000
Facility Latitude:	35 50 6.0000	Facility Longitude:	106 9 3.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

PWS ID:	NM3505126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANGRE DE CRISTO WATER COMPANY		
	PO BOX 4670		
	SANTA FE, NM 87502		

Source: Surface water	
Treatment Objective: CORROSION CONTROL	Process: PH ADJUSTMENT, POST
Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Treatment Objective: OTHER

Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude: 35 39 32.0000
 Facility Latitude: 35 40 21.0000
 Facility Latitude: 35 40 33.0000
 Facility Latitude: 35 40 41.0000
 Facility Latitude: 35 41 4.0000
 Facility Latitude: 35 41 9.0000
 Facility Latitude: 35 41 18.0000
 Facility Latitude: 35 48 54.0000
 Facility Latitude: 35 49 8.0000
 Facility Latitude: 35 49 13.0000
 Facility Latitude: 35 49 46.0000
 Facility Latitude: 35 49 53.0000
 Facility Latitude: 35 50 5.0000
 Facility Latitude: 35 50 6.0000
 City Served: Not Reported
 Treatment Class: Treated

Facility Longitude: 105 57 54.0000
 Facility Longitude: 105 58 48.0000
 Facility Longitude: 105 57 43.0000
 Facility Longitude: 105 58 15.0000
 Facility Longitude: 105 58 0.0000
 Facility Longitude: 105 57 37.0000
 Facility Longitude: 105 57 25.0000
 Facility Longitude: 106 8 53.0000
 Facility Longitude: 106 8 44.0000
 Facility Longitude: 106 8 53.0000
 Facility Longitude: 106 9 20.0000
 Facility Longitude: 106 9 55.0000
 Facility Longitude: 106 9 28.0000
 Facility Longitude: 106 9 3.0000

Population: 60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100750	Enforcement ID:	0200949
Enforcement Date:	2002-04-29	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

PWS ID:	NM3505126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANGRE DE CRISTO WATER COMPANY		
	PO BOX 4670		
	SANTA FE, NM 87502		

Source: Surface water

Treatment Objective: CORROSION CONTROL

Process: PH ADJUSTMENT, POST

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Treatment Objective: DISINFECTION	Process: GASEOUS CHLORINATION, POST
Treatment Objective: PARTICULATE REMOVAL	Process: COAGULATION
Treatment Objective: PARTICULATE REMOVAL	Process: FILTRATION, RAPID SAND
Treatment Objective: PARTICULATE REMOVAL	Process: SEDIMENTATION
Treatment Objective: TASTE / ODOR CONTROL	Process: ACTIVATED CARBON, POWDERED
Treatment Objective: OTHER	Process: FLUORIDATION

Addressee / Facility: Not Reported

Facility Latitude: 35 39 32.0000	Facility Longitude: 105 57 54.0000
Facility Latitude: 35 40 21.0000	Facility Longitude: 105 58 48.0000
Facility Latitude: 35 40 33.0000	Facility Longitude: 105 57 43.0000
Facility Latitude: 35 40 41.0000	Facility Longitude: 105 58 15.0000
Facility Latitude: 35 41 4.0000	Facility Longitude: 105 58 0.0000
Facility Latitude: 35 41 9.0000	Facility Longitude: 105 57 37.0000
Facility Latitude: 35 41 18.0000	Facility Longitude: 105 57 25.0000
Facility Latitude: 35 48 54.0000	Facility Longitude: 106 8 53.0000
Facility Latitude: 35 49 8.0000	Facility Longitude: 106 8 44.0000
Facility Latitude: 35 49 13.0000	Facility Longitude: 106 8 53.0000
Facility Latitude: 35 49 46.0000	Facility Longitude: 106 9 20.0000
Facility Latitude: 35 49 53.0000	Facility Longitude: 106 9 55.0000
Facility Latitude: 35 50 5.0000	Facility Longitude: 106 9 28.0000
Facility Latitude: 35 50 6.0000	Facility Longitude: 106 9 3.0000
City Served: Not Reported	
Treatment Class: Treated	Population: 60000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name: SANTA FE WATER SYSTEM (CITY OF)	
Violation Type: Monitoring, Regular	
Contaminant: TTHM	
Compliance Period: 2001-07-01 - 2001-07-31	Analytical Value: 0
Violation ID: 0100750	Enforcement ID: 0200949
Enforcement Date: 2002-04-29	Enf. Action: State Compliance Achieved
System Name: SANTA FE WATER SYSTEM (CITY OF)	
Violation Type: Monitoring, Regular	
Contaminant: TTHM	
Compliance Period: 2001-07-01 - 2001-07-31	Analytical Value: 0
Violation ID: 0100750	Enforcement ID: 0200949
Enforcement Date: 2002-04-29	Enf. Action: State Compliance Achieved
System Name: SANTA FE WATER SYSTEM (CITY OF)	
Violation Type: Monitoring, Regular	
Contaminant: TTHM	
Compliance Period: 2001-07-01 - 2001-07-31	Analytical Value: 0
Violation ID: 0500751	Enforcement ID: 0200819
Enforcement Date: 2002-04-29	Enf. Action: State Violation/Reminder Notice
System Name: SANTA FE WATER SYSTEM (CITY OF)	
Violation Type: Monitoring, Regular	
Contaminant: TTHM	
Compliance Period: 2001-07-01 - 2001-07-31	Analytical Value: 0
Violation ID: 0500751	Enforcement ID: 0200820
Enforcement Date: 2002-04-29	Enf. Action: State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0200948
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Received
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500751	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500752	Enforcement ID:	0200820
Enforcement Date:	2002-04-29	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TTHM		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0500753	Enforcement ID:	0200819
Enforcement Date:	2002-04-29	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500754	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CYANIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500755	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500756	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500757	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDRIN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500758	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500759	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500760	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BHC-GAMMA (LINDANE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500761	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500762	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500763	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	METHOXYCHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500764	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500765	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500766	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOXAPHENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500767	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500768	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500769	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DALAPON		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500770	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500771	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500772	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DIQUAT		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500773	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500774	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500775	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ENDOTHALL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500776	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500777	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500778	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	GLYPHOSATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500779	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500780	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500781	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DI (2-ETHYLHEXYL) ADIPATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500782	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500783	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500784	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	OXAMYL (VYDATE)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500785	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500786	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500787	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	SIMAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500788	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500789	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500790	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOLOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500993
Enforcement Date:	2005-04-05	Enf. Action:	State Formal NOV Issued
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCLOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCLOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500994
Enforcement Date:	2005-04-05	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PICLORAM		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	DINOSEB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CHLORDANE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ETHYLENE DIBROMIDE (EDB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	1,2 DIBROMO-3-CHLOROPROPANE (DBCP)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1260		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1254		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1248		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1242		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1232		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1221		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	AROCOR 1016		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	TOTAL POLYCHLORINATED BIPHENYLS (PCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	PENTACHLOROPHENOL		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BENZO (A) PYRENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	BIS (2-ETHYLHEXYL) PHTHALATE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROBENZENE (HCB)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4,5-TP (SILVEX)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,4-D		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEPTACHLOR EPOXIDE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	2,3,7,8-TCDD (DIOXIN)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALACHLOR (LASSO)		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ATRAZINE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	CARBOFURAN		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	ALDICARB SULFONE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved
System Name:	SANTA FE WATER SYSTEM (CITY OF)		
Violation Type:	Monitoring, Regular		
Contaminant:	HEXACHLOROCYCLOPENTADIENE		
Compliance Period:	2002-01-01 - 2004-12-31	Analytical Value:	0
Violation ID:	0500791	Enforcement ID:	0500997
Enforcement Date:	2005-04-13	Enf. Action:	State Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NM3571426 PWS Status: Not Reported
 Date Initiated: Not Reported Date Deactivated: Not Reported
 PWS Name: LONE STAR MOBILE HOME PARK
 ROUTE 6, BOX 24
 SANTA FE, NM 87501

Addressee / Facility: Not Reported

Facility Latitude: 35 39 14.0000 Facility Longitude: 106 1 35.0000
 City Served: Not Reported
 Treatment Class: Untreated Population: 95

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name: LONE STAR TRAILER RANCH
 Violation Type: CCR Complete Failure to Report
 Contaminant: 7000
 Compliance Period: 1999-10-19 - 2000-01-05 Analytical Value: 0
 Violation ID: 00V0001 Enforcement ID: 0599999
 Enforcement Date: 2000-01-05 Enf. Action: Fed Compliance Achieved

System Name: LONE STAR MOBILE HOME PARK
 Violation Type: CCR Complete Failure to Report
 Contaminant: 7000
 Compliance Period: 1999-10-19 - 2015-12-31 Analytical Value: 0000000.000000000
 Violation ID: 00V0001 Enforcement ID: Not Reported
 Enforcement Date: Not Reported Enf. Action: Not Reported

System Name: LONE STAR MOBILE HOME PARK
 Violation Type: CCR Complete Failure to Report
 Contaminant: 7000
 Compliance Period: 1999-10-19 - 2015-12-31 Analytical Value: 0
 Violation ID: 00V0001 Enforcement ID: Not Reported
 Enforcement Date: Not Reported Enf. Action: Not Reported

System Name: LONE STAR MOBILE HOME PARK
 Violation Type: Monitoring, Repeat Minor (TCR)
 Contaminant: COLIFORM (TCR)
 Compliance Period: 1994-07-01 - 1994-07-31 Analytical Value: 00000000.00
 Violation ID: 9400845 Enforcement ID: 9401149
 Enforcement Date: 1994-11-28 Enf. Action: State Public Notif Issued

System Name: LONE STAR MOBILE HOME PARK
 Violation Type: Monitoring, Repeat Minor (TCR)
 Contaminant: COLIFORM (TCR)
 Compliance Period: 1994-07-01 - 1994-07-31 Analytical Value: 00000000.00
 Violation ID: 9400845 Enforcement ID: 9401150
 Enforcement Date: 1994-08-11 Enf. Action: State Public Notif Requested

System Name: LONE STAR MOBILE HOME PARK
 Violation Type: Monitoring, Repeat Minor (TCR)
 Contaminant: COLIFORM (TCR)
 Compliance Period: 1994-07-01 - 1994-07-31 Analytical Value: 00000000.00
 Violation ID: 9400845 Enforcement ID: 9401151
 Enforcement Date: 1994-09-30 Enf. Action: State Tech Assistance Visit

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Repeat Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-07-01 - 1994-07-31	Analytical Value:	00000000.00
Violation ID:	9400845	Enforcement ID:	9500001E
Enforcement Date:	1995-01-24	Enf. Action:	Fed Formal NOV Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400846	Enforcement ID:	9401149
Enforcement Date:	1994-11-28	Enf. Action:	State Public Notif Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400846	Enforcement ID:	9401150
Enforcement Date:	1994-08-11	Enf. Action:	State Public Notif Requested
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400846	Enforcement ID:	9401151
Enforcement Date:	1994-09-30	Enf. Action:	State Tech Assistance Visit
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400846	Enforcement ID:	9500001E
Enforcement Date:	1995-01-24	Enf. Action:	Fed Formal NOV Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Repeat Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400847	Enforcement ID:	9401149
Enforcement Date:	1994-11-28	Enf. Action:	State Public Notif Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Repeat Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400847	Enforcement ID:	9401150
Enforcement Date:	1994-08-11	Enf. Action:	State Public Notif Requested
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Repeat Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400847	Enforcement ID:	9401151
Enforcement Date:	1994-09-30	Enf. Action:	State Tech Assistance Visit

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Repeat Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-08-01 - 1994-08-31	Analytical Value:	00000000.00
Violation ID:	9400847	Enforcement ID:	9500001E
Enforcement Date:	1995-01-24	Enf. Action:	Fed Formal NOV Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-09-01 - 1994-09-30	Analytical Value:	00000000.00
Violation ID:	9400848	Enforcement ID:	9401149
Enforcement Date:	1994-11-28	Enf. Action:	State Public Notif Issued
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-09-01 - 1994-09-30	Analytical Value:	00000000.00
Violation ID:	9400848	Enforcement ID:	9401151
Enforcement Date:	1994-09-30	Enf. Action:	State Tech Assistance Visit
System Name:	LONE STAR MOBILE HOME PARK		
Violation Type:	Monitoring, Routine Minor (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1994-09-01 - 1994-09-30	Analytical Value:	00000000.00
Violation ID:	9400848	Enforcement ID:	9500001E
Enforcement Date:	1995-01-24	Enf. Action:	Fed Formal NOV Issued

PWS ID:	NM3565926	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SUNSET MOBILE HOME PARK (SANTA FE) 528 AIRPORT ROAD #15 SANTA FE, NM 87505		

Addressee / Facility: Not Reported

Facility Latitude:	35 38 23.0000	Facility Longitude:	106 1 12.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	135

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SUNSET MOBILE HOME PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NM3544526 PWS Status: Not Reported
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: SANTA FE COUNTRY CLUB APARTMENTS
1002 APRPORT RD.
SANTA FE, NM 87505

Addressee / Facility: Not Reported

Facility Latitude: 35 38 16.0000 Facility Longitude: 106 2 10.0000
Facility Latitude: 35 38 16.0000 Facility Longitude: 106 2 12.0000
City Served: Not Reported
Treatment Class: Untreated Population: 130

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name: SANTA FE COUNTRY CLUB APAR
Violation Type: CCR Complete Failure to Report
Contaminant: 7000
Compliance Period: 1999-10-19 - 2015-12-31 Analytical Value: 0000000.000000000
Violation ID: 0000001 Enforcement ID: Not Reported
Enforcement Date: Not Reported Enf. Action: Not Reported

System Name: SANTA FE COUNTRY CLUB APART
Violation Type: CCR Complete Failure to Report
Contaminant: 7000
Compliance Period: 1999-10-19 - 2015-12-31 Analytical Value: 0
Violation ID: 0000001 Enforcement ID: Not Reported
Enforcement Date: Not Reported Enf. Action: Not Reported

System Name: SANTA FE COUNTRY CLUB APARTMENTS
Violation Type: CCR Complete Failure to Report
Contaminant: 7000
Compliance Period: 1999-10-19 - 2015-12-31 Analytical Value: 0
Violation ID: 0000001 Enforcement ID: Not Reported
Enforcement Date: Not Reported Enf. Action: Not Reported

PWS ID: NM3544526 PWS Status: Not Reported
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: SANTA FE COUNTRY CLUB APARTMENTS
1002 APRPORT RD.
SANTA FE, NM 87505

Addressee / Facility: Not Reported

Facility Latitude: 35 38 16.0000 Facility Longitude: 106 2 10.0000
Facility Latitude: 35 38 16.0000 Facility Longitude: 106 2 12.0000
City Served: Not Reported
Treatment Class: Untreated Population: 130

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTRY CLUB APAR		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE COUNTRY CLUB APART		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE COUNTRY CLUB APARTMENTS		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

PWS ID:	NM3545326	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	CASITAS DE SANTA FE 521 AIRPORT ROAD SANTA FE, NM 87501		

Addressee / Facility: Not Reported

Facility Latitude:	35 38 12.0000	Facility Longitude:	106 1 41.0000
Facility Latitude:	35 38 13.0000	Facility Longitude:	106 1 38.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	1000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	CASITAS DE SANTA FE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	CASITAS DE SANTA FE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NM3545326 PWS Status: Not Reported
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: CASITAS DE SANTA FE
521 AIRPORT ROAD
SANTA FE, NM 87501

Addressee / Facility: Not Reported

Facility Latitude: 35 38 12.0000 Facility Longitude: 106 1 41.0000
Facility Latitude: 35 38 13.0000 Facility Longitude: 106 1 38.0000
City Served: Not Reported
Treatment Class: Untreated Population: 1000

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	CASITAS DE SANTA FE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	CASITAS DE SANTA FE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

PWS ID: NM3544626 PWS Status: Not Reported
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: COUNTRY CLUB GARDENS MOBILE HOME PARK
1002 AIRPORT RD.
SANTA FE, NM 87501

Addressee / Facility: Not Reported

Facility Latitude: 35 38 12.0000 Facility Longitude: 106 2 35.0000
City Served: Not Reported
Treatment Class: Untreated Population: 1100

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	COUNTRY CLUB GARDENS MOBIL		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	COUNTRY CLUB GARDENS MOBILE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	COUNTRY CLUB GARDENS MOBIL		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	COUNTRY CLUB GARDENS MOBIL		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	1998-10-01 - 1998-10-31	Analytical Value:	0000000.000000000
Violation ID:	99000103	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

PWS ID:	NM3569826	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	ASI LA MAR TRAILER PARK		
	181 AIRPORT ROAD		
	SANTA FE, NM 87501		

Addressee / Facility: Not Reported

Facility Latitude:	35 38 1.0000	Facility Longitude:	106 2 13.0000
Facility Latitude:	35 38 1.0000	Facility Longitude:	106 2 14.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	80

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2000-10-30	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	0599999
Enforcement Date:	2000-10-30	Enf. Action:	Fed Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100254	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100254	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100255	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100255	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100256	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100256	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received

PWS ID:	NM3569826	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	ASI LA MAR TRAILER PARK		
	181 AIRPORT ROAD		
	SANTA FE, NM 87501		

Addressee / Facility: Not Reported

Facility Latitude:	35 38 1.0000	Facility Longitude:	106 2 13.0000
Facility Latitude:	35 38 1.0000	Facility Longitude:	106 2 14.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	80

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2000-10-30	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	0599999
Enforcement Date:	2000-10-30	Enf. Action:	Fed Compliance Achieved

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	00V0001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100254	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100254	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100255	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100255	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-04-01 - 2001-04-30	Analytical Value:	0
Violation ID:	0100256	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100256	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100874
Enforcement Date:	2001-08-08	Enf. Action:	State Violation/Reminder Notice
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100875
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Requested
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-05-01 - 2001-05-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received
System Name:	ASI LA MAR TRAILER PARK		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-07-01 - 2001-07-31	Analytical Value:	0
Violation ID:	0100366	Enforcement ID:	0100876
Enforcement Date:	2001-08-08	Enf. Action:	State Public Notif Received

PWS ID:	NM3570526	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	JEMEZ ROAD MOBILE HOME PARK		
	507 JEMEZ ROAD, SPACE #40		
	SANTA FE, NM 87505		

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Addressee / Facility:	Not Reported		
Facility Latitude:	35 37 52.0000	Facility Longitude:	106 1 47.0000
Facility Latitude:	35 37 53.0000	Facility Longitude:	106 1 47.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	200
PWS currently has or had major violation(s) or enforcement:		No	

PWS ID:	NM3570526	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	JEMEZ ROAD MOBILE HOME PARK 507 JEMEZ ROAD, SPACE #40 SANTA FE, NM 87505		

Addressee / Facility:	Not Reported		
Facility Latitude:	35 37 52.0000	Facility Longitude:	106 1 47.0000
Facility Latitude:	35 37 53.0000	Facility Longitude:	106 1 47.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	200
PWS currently has or had major violation(s) or enforcement:		No	

PWS ID:	NM3570726	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANTA FE MOBILE HOME HACIENDA 1110 OCATE ROAD SPACE 110 SANTA FE, NM 87505		

Addressee / Facility:	Not Reported		
Facility Latitude:	35 37 24.0000	Facility Longitude:	106 1 52.0000
Facility Latitude:	35 37 26.0000	Facility Longitude:	106 1 55.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	450
PWS currently has or had major violation(s) or enforcement:		Yes	

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2002-06-20	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE MOBILE HOME HACIE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIEN		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2002-06-20	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	0599999
Enforcement Date:	2002-06-20	Enf. Action:	Fed Compliance Achieved

PWS ID:	NM3570726	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	SANTA FE MOBILE HOME HACIENDA 1110 OCATE ROAD SPACE 110 SANTA FE, NM 87505		

Addressee / Facility: Not Reported

Facility Latitude:	35 37 24.0000	Facility Longitude:	106 1 52.0000
Facility Latitude:	35 37 26.0000	Facility Longitude:	106 1 55.0000
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	450

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2002-06-20	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE MOBILE HOME HACIE		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIEN		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE MOBILE HOME HACIENDA		
Violation Type:	CCR Inadequate Reporting		
Contaminant:	7000		
Compliance Period:	2001-10-01 - 2002-06-20	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	0599999
Enforcement Date:	2002-06-20	Enf. Action:	Fed Compliance Achieved

PWS ID:	NM3538126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	VALLE VISTA WATER UTILITY, INC. PO BOX 2468 SANTA FE, NM 87504		

Addressee / Facility: Not Reported

Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 25.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 27.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 28.0000

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 41.0000
Facility Latitude:	35 35 5.0000	Facility Longitude:	106 3 21.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	975

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY I		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY INC		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2002-07-01 - 2003-06-21	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0599999
Enforcement Date:	2003-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0598999
Enforcement Date:	2002-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

PWS ID:	NM3538126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	VALLE VISTA WATER UTILITY, INC. PO BOX 2468 SANTA FE, NM 87504		

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

Addressee / Facility:	Not Reported		
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 25.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 27.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 28.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 41.0000
Facility Latitude:	35 35 5.0000	Facility Longitude:	106 3 21.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	975

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0000000.000000000
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		
System Name:	VALLE VISTA WATER UTILITY I		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		
System Name:	VALLE VISTA WATER UTILITY INC		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		
System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0000000.000000000
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	Not Reported
Violation ID:	0000001	Enf. Action:	Not Reported
Enforcement Date:	Not Reported		

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2002-07-01 - 2003-06-21	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0599999
Enforcement Date:	2003-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0598999
Enforcement Date:	2002-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NM3538126 PWS Status: Not Reported
 Date Initiated: Not Reported Date Deactivated: Not Reported
 PWS Name: VALLE VISTA WATER UTILITY, INC.
 PO BOX 2468
 SANTA FE, NM 87504

Addressee / Facility: Not Reported

Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 25.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 27.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 28.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 41.0000
Facility Latitude:	35 35 5.0000	Facility Longitude:	106 3 21.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	975

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY I		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY INC		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2002-07-01 - 2003-06-21	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0599999
Enforcement Date:	2003-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0598999
Enforcement Date:	2002-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	2001-07-01 - 2002-06-21	Enforcement ID:	02E0001
Violation ID:	0270001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2002-06-20		

PWS ID:	NM3538126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	VALLE VISTA WATER UTILITY, INC. PO BOX 2468 SANTA FE, NM 87504		

Addressee / Facility: Not Reported

Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 25.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 27.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 28.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 41.0000
Facility Latitude:	35 35 5.0000	Facility Longitude:	106 3 21.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	975

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0000000.000000000
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		

System Name:	VALLE VISTA WATER UTILITY I		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		

System Name:	VALLE VISTA WATER UTILITY INC		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000	Analytical Value:	0
Compliance Period:	1999-10-19 - 2015-12-31	Enforcement ID:	00E0001
Violation ID:	0000001	Enf. Action:	Fed Formal NOV Issued
Enforcement Date:	2000-05-05		

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2002-07-01 - 2003-06-21	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0599999
Enforcement Date:	2003-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0598999
Enforcement Date:	2002-06-21	Enf. Action:	Fed Compliance Achieved

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

PWS ID:	NM3538126	PWS Status:	Not Reported
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	VALLE VISTA WATER UTILITY, INC. PO BOX 2468 SANTA FE, NM 87504		

Addressee / Facility: Not Reported

Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 25.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 27.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 28.0000
Facility Latitude:	35 35 1.0000	Facility Longitude:	106 3 41.0000
Facility Latitude:	35 35 5.0000	Facility Longitude:	106 3 21.0000
City Served:	Not Reported		
Treatment Class:	Treated	Population:	975

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY I		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY INC		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0
Violation ID:	0000001	Enforcement ID:	00E0001
Enforcement Date:	2000-05-05	Enf. Action:	Fed Formal NOV Issued
System Name:	VALLE VISTA WATER UTILITY		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	1999-10-19 - 2015-12-31	Analytical Value:	0000000.000000000
Violation ID:	0000001	Enforcement ID:	Not Reported
Enforcement Date:	Not Reported	Enf. Action:	Not Reported
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2002-07-01 - 2003-06-21	Analytical Value:	0
Violation ID:	0100248	Enforcement ID:	0599999
Enforcement Date:	2003-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100675
Enforcement Date:	2001-07-03	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100676
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100677
Enforcement Date:	2001-07-03	Enf. Action:	State Public Notif Received
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200862
Enforcement Date:	2002-07-22	Enf. Action:	State Violation/Reminder Notice
System Name:	VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	Monitoring, Routine Major (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2002-06-01 - 2002-06-30	Analytical Value:	0
Violation ID:	0200255	Enforcement ID:	0200863
Enforcement Date:	2002-07-22	Enf. Action:	State Public Notif Requested
System Name:	VALLE VISTA		
Violation Type:	MCL, Acute (TCR)		
Contaminant:	COLIFORM (TCR)		
Compliance Period:	2001-06-01 - 2001-06-30	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0100678
Enforcement Date:	2001-07-03	Enf. Action:	State Boil Water Order

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

ENFORCEMENT INFORMATION:

System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0200805	Enforcement ID:	0598999
Enforcement Date:	2002-06-21	Enf. Action:	Fed Compliance Achieved
System Name:	VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2015-12-31	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued
System Name:	SANTA FE COUNTY UTILITIES@VALLE VISTA		
Violation Type:	CCR Complete Failure to Report		
Contaminant:	7000		
Compliance Period:	2001-07-01 - 2002-06-21	Analytical Value:	0
Violation ID:	0270001	Enforcement ID:	02E0001
Enforcement Date:	2002-06-20	Enf. Action:	Fed Formal NOV Issued

NEW MEXICO GOVERNMENT WELL RECORDS SEARCHED

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

State Database: NM Radon

Source: Environment Department

Telephone: 505-827-1093

Radon Test Results

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

Oil and Gas Well Locations

Source: New Mexico Institute of Mining and Technology

Telephone: 505-835-5142

Water Well Database

Source: Office of the State Engineer

Telephone: 505-827-6175

STREET AND ADDRESS INFORMATION

© 2004 Geographic Data Technology, Inc., Rel. 07/2004. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.